Tő:	· 051095	API NUMBER 15- 025-20,932-00-00		
CONSERVAT	PORATION COMMISSION ION DIVISION - PLUGGING SECTION ADO DERBY BUILDING			31 S, R 24 WXXX
	KANSAS 67202			m S section line
TECHNICIA	N'S PLUGGING REPORT .			n E section line
Operator 1	License # 5703	Lease Name_Alle		
Nemal	J.M. Huber Corporation	and the second s		188.50
	7120 I-40 West, Suite 232	Well Total Dept	h580	<u> </u>
	Amarillo, TX 79106	Conductor Pipe:	Slze	feet
		Surface Casing:	\$1ze ^{8 5/8}	feet 1700
Abandonød	Oli Weil X	Input Well	SWD Well_	D&A
Other wel	l as hereinafter indicated			
Plugging	Contractor Bruce Well Service		License N	umber
	Box 1597, Liberal, KS 67901			
Company †	o plug at: Hour:8 a.m. Day:_	12Month:	10	Year:19_88
Plugging	proposal received from Jerry Tro	out DECEIVED	SION	
(company name) J.M. Huber Corporation STATE CORPORATION COMMISSION Were: 5½" at 5798' PBTD 5750' Perfs at 5654-57'007 1 8 1988				
vere: 5½	" at 5798' PBTD 5750' Perfs at	5654-57'00T 1 8 198'	<i>B</i>	
		المحاجم المحاجم	-98	
2nd plice	displace hole through tubing wit	h mud regiservation on	as tubing af	ter nulling casing
	sx cement at 1730-1630',	D-FO-Mileman	<u> </u>	ber pulling eduling
	at 850' with 50 sx cement, 4th p	lug at 40' with 10	sx cement.	
	Division Projection	posal Received by	Richard	d Lacev
		OSSI KACATYAL DY	(TE	CHNICIAN)
Plugging	Operations attended by Agent?: /	NIIPart_	X.	None
Operation	is Completed: Hour: 10:30 a.மிகு:	12	10	Year:19 88
ACTUAL PL	UGGING REPORT 1st plug set CIE	P at 5635' with 2 s	x cement of	n top,
2nd plug	displace hole through tubing wit	h mud, plugged thro	ugh tubing	after pulling
casing w	ith 100 sx cement at 1730-1630'.			
	at 850' with 50 sx cement,	,		
Boom-ke Us	sed Class H cement by Halliburton	Recovered 2800'	of 5½" cas:	ing.
Walley .	sed Class H cement by Halliburton (if additional description is	s necessary, use <u>BAC</u>	CK of this	form.)
	observe this plugging.	Signed Richard	1 av	P
re	1-27-88	Signed Milhar	TECHNICI	AND THE THE