

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Stickle Drilling Co. Address 507 Bitting Building
(Applicant)

Lease (Farm Name) Crosley Well No. 1

Well Location SE SE SE Sec. 1 Twp. 28 Rge. 12 (X) - (W)

County Pratt County, Kansas Field Name (if any) _____

Total Depth 4595 Oil ___ Gas ___ Dry Hole ___ Dry Hole

Was well log filed with application? ___ If not, explain: _____

Will be filed with Well Plugging Record

Date and hour plugging is desired to begin 3 a.m. December 3, 1955

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

H.C. Hickman Address 2115 Jackson, Great Bend, Kans.

Plugging Contractor Stickle Drilling Company

Plugging Contractor's License No. _____

Address 507 Bitting Building, Wichita 2, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Stickle Drilling Company Address 507 Bitting Building, Wichita, Ks.

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
DEC 28 1955
CONSERVATION DIVISION
WICHITA, KANSAS
12-28-55

R. B. Parriott
Applicant or Acting Agent

Date 3 December 1955

PLUGGING
FILE SEC L T 28 R 12 W
BOOK PAGE 22 LINE 18



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS
December 7, 1955

Well No.	1
Lease	Crosley
Description	SE SE SE Sec. 1-28-12W
County	Pratt
File No.	22-18

Stickle Drilling Company
507 Bittling Bldg.,
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. H. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By

S. S. Greider

WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor