STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission 800 Bitting Building

WELL PLUGGING RECORD


800 Bitting Building Wichita, Kansas	Kingn	nan	Count	y. Sec. 24 T	wp. 30 Rge	e (E)_	⁵ (W)
NORTH	Location as "NI	E/CNW%SW%"	or footage fro	m lines NE	<u>SE SW</u>		
! ! !	1	~ ~ 1		g Company			
	Lease Name			Olalaham		Well No	I
	1			Oklahom :		1 -	
	Character of W	ell (completed pleted 10-1	as Oil, Gas o	r Dry Hole)	Dry_no.	<u>re</u>	19 59
i i ·		plugging filed					_195
	Application for	plugging approv	ved 10-1	0	_		_195°
i [i	Plugging comm	enced 10-	10				19 5'
Į {	Plugging compl	leted10-	-10				₁₉ 5
 	Reason for abar	ndonment of wel	ll or producin	g formation $\underline{\hspace{1cm}}^{\hspace{1cm} \hspace{1cm} \hspace{1cm}}$	<u>Ory hole</u>		
i i	_ 						
				st production			
Locate well correctly on above				ation Division of	r its agents be	fore plugging	was com
Section Plat ne of Conservation Agent who super		a wall					
lucing formation.						5 Wall 466	5 F
v depth and thickness of all water,			Docton		Total Depth o	i wen <u>ago</u>	∠ ree
•	_				£		
OIL, GAS OR WATER RECORDS	S 			 		CASING RE	CORD
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED	דעם
	ь			8-5/8	248	None	<u> </u>
• •		ļ	-				
		<u> </u>	ļ				
· · · · · · · · · · · · · · · · · · ·			 			 	,
		<u> </u>	 				
		 	 	 			
			 	 			
feet for each plug set	ent or other plugs we t. with mud to plug with Hal	300'. Set	bridge a	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	300'. Set	bridge a	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	3001. Set liburton. th cement	bridge a	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	ent or other plugs we t. with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	of same and depth and plug @ aloole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
feet for each plug set Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
feet for each plug set Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set liburton. th cement	bridge a Filled h to surfa	and plug @ cole with m	3001. Pt	ımped	
Filled hole 20 sacks cement on	with mud to plug with Hal	300'. Set 300'. Set liburton. th cement OPPORATION CO JAN 1 9 1	bridge a Filled h to surfa	and plug @ note with more.	3001. Pt	ımped	
Filled hole 20 sacks cement on bridge and plug @ 40	with mud to plug with Hal	300'. Set 300'. Set liburton. th cement CAN 1 9 CERVATION W. In the content of	bridge a Filled h to surfa	and plug @ note with more.	3001. Pt	ımped	
Filled hole 20 sacks cement on bridge and plug @ 40	with mud to plug with Hal	300'. Set 300'. Set liburton. th cement CONDORATION CO JAN 1 9 1 CERVATION Wight Comp	bridge a Filled h to surfa	and plug @ note with more.	3001. Pt	ımped	
Filled hole 20 sacks cement on bridge and plug @ 40	with mud to plug with Hal TIME C (If additional Herndon Dril	300'. Set 300'. Set liburton. th cement CONDORATION CO JAN 1 9 1 CERVATION Wight Comp	bridge a Filled h to surfa	and plug @ note with more.	3001. Pt	ımped	
ress rest for each plug introducing it into the hole. If ceme feet for each plug set Filled hole 20 sacks cement on bridge and plug @ 40 feet for each plug set feet feet for each plug set feet feet feet feet feet feet feet	with mud to plug with Hal The control of the contr	300'. Set 300'. Set liburton. th cement OPPORATION OF JAN 1 9 INCREMATION INCRE	bridge a Filled h to surfa	and plug @ note with more.	3001. Pt	ımped	
ress TE OF OKLAHOMA	with mud to plug with Hal The control of the contr	300'. Set 300'. Set liburton. th cement COMPORATION CO JAN 1 9 1 Gescription is nece ling Comp lsa, Oklal	bridge a Filled h to surfa NICLE 1 PIVISION 1-1 PIVISIO	and plug @ with mode.	a placed, from 300°. Pund to 40°	imped . Set	feet t
ress TE OF OKLAHOMA W. G. Prather	with mud to plug with Hal Filled with Hal CON (If additional Herndon Dril Box 489, Tu	300'. Set 300'. Set liburton. th cement Opporation of JAN 1 9 1	bridge a Filled h to surfa Milled h to surfa Pivision Pivision Bridge a Filled h to surfa TULSA Employee of	and plug @ Lind plug & Lind pl	a placed, from 300°. Pund to 40° nud to 40°	imped . Set	feet t
Filled hole Filled hole 20 sacks cement on bridge and plug @ 40 The of Plugging Contractor The of OKLAHOMA W. G. Prather being first duly sworn on oath, sa	with mud to plug with Hallow. Filled with Hallow. COM (If additional Herndon Dril Box 489, Tu , COU	300'. Set 300'. Set liburton. th cement AN 1 0 1 AN 1	bridge a Filled h to surfa Milled h to surfa Milled h TOULSA Employee of facts, statement	of this sheet)	a placed, from 300°. Pund to 40° nud to 40°	imped . Set	feet t
Filled hole Filled hole 20 sacks cement on bridge and plug @ 40 The of Plugging Contractor The of OKLAHOMA W. G. Prather being first duly sworn on oath, sa	with mud to plug with Hallow. Filled with Hallow. COM (If additional Herndon Dril Box 489, Tu , COU	JAN 1 9 1 Gescription is necelling Compation (Compation) Idescription is necelling Compation (Compation) Open C	bridge a Filled h to surfa Milled h to surfa Milled h TOULSA Employee of facts, statement	of this sheet)	a placed, from 300°. Pund to 40° nud to 40°	imped . Set	feet t
ress	with mud to plug with Hallow. Filled with Hallow. COM (If additional Herndon Dril Box 489, Tu , COU	300'. Set 300'. Set liburton. th cement AN 1 0 1 AN 1	bridge a Filled h to surfa Millian GSO \-\ DIVISION BESTY, use BACK DANY homa TULSA employee of facts, statement of the pure God.	of this sheet)	a placed, from 300°. Pund to 40° nud to 40°	imped . Set	feet t
Filled hole Filled hole 20 sacks cement on bridge and plug @ 40 The of Plugging Contractor The of OKLAHOMA W. G. Prather being first duly sworn on oath, sa	with mud to plug with Hallow. Filled with Hallow. COM (If additional Herndon Dril Box 489, Tu , COU	JAN 1 9 1 Gescription is necelling Compation (Compation) Idescription is necelling Compation (Compation) Open C	bridge a Filled h to surfa Millian GSO \-\ DIVISION BESTY, use BACK DANY homa TULSA employee of facts, statement of the pure God.	and plug @ wole with m ce. of this sheet) owner) or (owners, and matters, s, Kansas	s, ss. er or operator)	imped . Set	feet to
reducing it into the hole. If cemefeet for each plug set Filled hole 20 sacks cement on bridge and plug @ 40 The of Plugging Contractor	with mud to plug with Hall of the same are true and the same are t	description is necelling Computation (Signature)	bridge a Filled h to surfa Millian OSO 1-1 PIVISION SSSARY, USE BACK DAINY homa TULSA employee of facts, statement of the surfa Lyons	and plug @ with mode. A-UD owner) or (owners, and matters, s., Kansas	, ss. er or operator) s-herein conta	of the above	feet t
ress TE OF OKLAHOMA W. G. Prather set for each plug into the hole. If cemerate feet for each plug set Filled hole 20 sacks cement on bridge and plug @ 40 and plug @ 40 bridge and plug @ 40 The of Plugging Contractor The of OKLAHOMA W. G. Prather The being first duly sworn on oath, so	with mud to plug with Hall of the same are true and the same are t	JAN 1 9 1 Gescription is necelling Compation (Compation) Idescription is necelling Compation (Compation) Open C	bridge a Filled h to surfa Millian OSO 1-1 PIVISION SSSARY, USE BACK DAINY homa TULSA employee of facts, statement of the surfa Lyons	and plug @ with mode. A-UD owner) or (owners, and matters, s., Kansas	, ss. er or operator) s-herein conta	imped . Set	-describer
ress TE OF OKLAHOMA W. G. Prather being first duly swom on oath, save-described well as filed and that	with mud to plug with Hall of the same are true and the same are t	description is necelling Computation (Signature)	bridge a Filled h to surfa Millian OSO 1-1 PIVISION SSSARY, USE BACK DAINY homa TULSA employee of facts, statement of the surfa Lyons	and plug @ with mode. A-UD owner) or (owners, and matters, s., Kansas	, ss. er or operator) s-herein conta	of the above	-describer

15-095-00360-0000

Plugged with 20 sacks cement @ 300'. Plugged with 10 sacks cement @ 40'.

WELL LOG

Well: Location: Owner:	R. SNELLING NO. 1 NE SE SW, SECTION 24-305-5W, KINGMAN COUNTY, KANSAS HERNDON DRILLING COMPANY		Spudding date: Date casing set: Date rotary completed: Date cable completed:	9-23-59 9-24-59 10-10-59
FROM	то	FORMATION	REMARKS	
0	351	Surface Hole		8" J-S 24# National Tube
351	590	Shale and Shells	Casing. Set @ 246	Cemented w/250 sx.
590	3455	Lime and Shale	Common cement?	8
3 4 55	4665	Lime		



Subscribed and sworn to before me this 19th

day of

4665

Total Depth

I certify the above and foregoing to be a true and exact copy
of the original driller's log on the P. SNELLING NO. 1

HERNDON DRILLING COMPANY

ry Public

My commission expires:

June 19, 1961

Asst. Secty.