STATE CORPOR	1 0/0032	•	API NUMBER 15-	7.5 20, 13.		
CONSERVATION 200 COLORADO	RATION COMMISSION N DIVISION - PLUGG O DERBY BUILDING NSAS 67202			5, •T	32 s, R	
•	S PLUGGING REPORT		660			
	cense # 5952 _		Lease Name Edna			
•	Amoco Production		CountyS			
Name&						
_	P. 0. Box 432, Liberal, KS 67901		Well Total Dept			
	2100141, 10 07501		Conductor Pipe:			_
— Abandoned O	II Well X	Gas Well	Surface Casing:			
other well	as hereinafter ind	dicated				
Plugging Co	ntractor <u>Midwest</u>	Casing Pulling	· · · · · · · · · · · · · · · · · · ·	_ License Numb	er	6497_
Address	P. O. Box F, Subl	lette, KS 67877				
	plug at: Hour: 10:			ctober)	'ear:19	85
	oposal received fr				216-67	
(company na	me)Midwest			(phone)	
were: 5 1/	2" at 6000' PBTD 5	5948 ' Perfs at 5	780-5792 Pump th	rough 5 1/2"	with mud l	between
1st plug	set CIBP at 5700'	with 2 sx cemen	plugs			
2nd plug	on stub with 50 sx	x cement				-
• -	at 1676 with 50 sx			-		
4th plug	at 720 with 40 sx solid bridge - hul	x cement Lls - plug at 40)		·	
	cement to surface	_Plugging Propo	sai Received by <u>Da</u>	an Goodrow (TECHI	NICIAN)	
oth plug	with 10 sx cement) X Pas+	Ne		
		by Agent?: Al	i Fail	- 110	one	
Plugging Op	erations attended					
Plugging Op Operations	erations attended Completed: Hour:	<u>5:00 pm Day:</u>	18 Month: 0	ctober	fear:19	85
Plugging Op Operations ACTUAL PLUG	erations attended Completed: Hour:_ GING REPORT 1st p	<u>5:00 pm Day:</u> plug at 2530' wi	18 Month: 0 th 50 sx cement,	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3	erations attended Completed: Hour: GING REPORT 1st p rd plug at 720° wi	5:00 pm Day: plug at 2530' wi ith 40 sx cement	Month: On the second of the se	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3	erations attended Completed: Hour:_ GING REPORT 1st p	5:00 pm Day: plug at 2530' wi ith 40 sx cement	Month: On the second of the se	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3	erations attended Completed: Hour: GING REPORT 1st p rd plug at 720° wi	5:00 pm Day: plug at 2530' wi ith 40 sx cement	Month: On the second of the se	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3	erations attended Completed: Hour: GING REPORT 1st p rd plug at 720° wi	5:00 pm Day: plug at 2530' wi ith 40 sx cement	Month: On the second of the se	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3	erations attended Completed: Hour: GING REPORT 1st p rd plug at 720° wi	5:00 pm Day: plug at 2530' wi ith 40 sx cement	Month: On the second of the se	ctober \china \china 2nd plug at 10	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3 plug at 4	cerations attended Completed: Hour:_ GING REPORT 1st p rd plug at 720' wi O' cement to su	5:00 pm Day: plug at 2530' wi ith 40 sx cement urface with 10 s	18 Month: On the theorem 18 Month: On the the the theorem 18 Month: On	ctober 2nd plug at 10 - solid brid	fear:19	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3 plug at 4 Remarks: R	Completed: Hour:_GING REPORT_1st prd plug at 720' wind o' cement to su	5:00 pm Day: plug at 2530' wi ith 40 sx cement urface with 10 s	18 Month: On the State of Common Cement by	ctober 2nd plug at 10 - solid brid	fear:19676' with ge - hull:	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3 plug at 4 Remarks: R	Completed: Hour:_GING REPORT_1st prd plug at 720' wind o' cement to su	5:00 pm Day: plug at 2530' wi ith 40 sx cement urface with 10 s	18 Month: On the State of Common Cement by	ctober 2nd plug at 10 - solid brid	fear:19676' with ge - hull:	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3 plug at 4 Remarks: R	completed: Hour: GING REPORT 1st p rd plug at 720' wi O' cement to su ecovered 2530' 5 1 (If additional of the complete subserved subserved the complete subserved subserve	5:00 pm Day: plug at 2530' wi ith 40 sx cement urface with 10 s 1/2" casing. Use description is the plugging.	18 Month: On the State of Stat	etober 2nd plug at 10 - solid bridg y Midwest. K of this for	fear:19676' with ge - hull:	85 50 sx
Plugging Op Operations ACTUAL PLUG cement, 3 plug at 4 Remarks: R	completed: Hour: GING REPORT 1st p rd plug at 720' wi O' cement to su ecovered 2530' 5 1 (If additional of the complete subserved subserved the complete subserved subserve	5:00 pm Day: plug at 2530' wi ith 40 sx cement urface with 10 s 1/2" casing. Use description is the plugging its plugging.	18 Month: On the State of Common Cement by	ctober 2nd plug at 10 - solid brid	(ear:19676' with ge - hull:	85 50 sx