LEASE	Grace
LICHOU	Inrace

SEC. 5 TWP. 335 RGE. 29W

FIL Show all important x cluding depth intorva	L IN WELL, ones of porosity a l rested, cushion u	nd contonts the	reof; cared into	rvals, and all	drill-s tres, a		SHOW GEOLOG OR OTHER DE	ICAL MARKERS, LOGS RUN, SCRIPTIVE INFORMATION.	
FORMAT10	N DESCRIPTION,	CONTENTS, ETC	• (ТОР	\Box	воттом	NAME	PEPTH	
<u>X</u> Check if	no Drill	Stem Test	s Run.		- 1				
	i				-				
HEEBNER (-1	754)			1,400					
				4420	j				
LANSING (-1890)				4556					
MARMATON (~2542)				5208					
MORROW (-3022)				·5688·					
MISSISSIPPIAN (-3135)			5801						
			-]				,	
		•		j	- }			ļ	
	•								
								•	
				•					
				Ì	-				
	•				- 1				
					- 1				
•									
•									
*1				Ì	- [
			•						
	•		7 0	0.1-0				•	
If additional	· Visit amin'in					(N)			
Report of all string	Size hole drilled			Setting depth	T -		or (Used	Type and percent	
Purpose of string	Size Role Brilled	Size casing sat	Weight 163/11.		↓	Type cemont 65 Pozmix/(50 6% gell 2%c.c.	
Surface	12½	8-5/8	24	·1568				<u> </u>	
					0	lass H	200	3% c.c.	
		<u> </u>							
	 			<u> </u>	 			 	
		<u> </u>	<u> </u>	<u> </u>					
LINER RECORD					PERFORA			TION RECORD	
op, ft.	lottom, ft.	Sacks ce	ement .	Shots	per f	t. Six	e & type	Depth Interval	
	TUBING RECO	ORD		1		1			
ilze	Setting depth	Packer	set at	-					
		CID, FRACT		CEMENT SQ	UEEZ	E RECORD			
	Amoi	unt and kind of	material used	, 		· · · · · · · · · · · · · · · · · · ·		pth interval treated	
, •		<u></u>	.	,	<u> </u>	·	 	_ .	
	est a large			•				•	
and the second	1 %				,,		1		
Date of first production '		Producin	g method (flow	ing, pumping,	gos ili	it, etc.)	Gravit		
D&A	- Louis						<u> </u>		
Estimated Production -I.	pated of P. P. Bobs. Gos				MCF	Water %	bbls.	s-oil ratio	
Disposition of gas (vented	, used on lease or	sold)				Perforation	ns		