

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Pickrell Drilling Co. Address 705 - 4th National Bank Bldg.
(Applicant)

Lease (Farm Name) Tiesmeyer Well No. 1

Well Location NE NE SE Sec. 1 Twp. 29 Rge. (E) 9 (W)

County Kingman Field Name (if any) _____

Total Depth 1735 Oil ___ Gas ___ Dry Hole X

Was well log filed with application? Yes If 'not, explain: _____

Date and hour plugging is desired to begin January 6, 1957, 6 P. M.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Cecil Burton Address 2820 Paseo, Great Bend, Kansas

Plugging Contractor Pickrell Drilling Company

Plugging Contractor's License No. _____

Address 705 - 4th National Bank Bldg., Wichita 2, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Pickrell Drilling Company Address 705 - 4th Nat'l. Bank, Wichita

and payment will be guaranteed by applicant.

1-12-57

RECEIVED
STATE CORPORATION COMMISSION

JAN 12 1957

CONSERVATION DIVISION
Applicant [Signature] Acting Agent

PLUGGING	
FILE	SEC <u>1</u> T. <u>29</u> R. <u>9W</u>
BOOK	PAGE <u>122</u> LINE <u>9</u>

Date January 11, 1957



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

January 8, 1957

Well No. 1
Lease Tiesmeyer
Description NE NE SE Sec. 1-29-9W
County Kingman
File No. 132-9

Pickrell Drilling Company
705 Fourth National Bank Bldg.,
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rifes, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor