TO: STATE CORPORATION COMMISSION

API NUMBER	15-189-	22,322	-0	50 -	00			
E/2 SW NE	SEC.	_11	, T	32	s,	R	39	W

CONSERVATION DIVISION - PLUGGING SECTION 1976 FEET FROM NORTH SECTION LINE
WICHITA STATE OFFICE BLDG., 130 S. MARKET 1469 FEET FROM EAST SECTION LINE
WICHITA, KANSAS 67202 LEASE NAME MLP SCHMIDT FARMS INC A WELL # 1
TECHNICIAN'S PLUGGING REPORT / COUNTY STEVENS 196.95
TECHNICIAN'S PLUGGING REPORT COUNTY STEVENS 76.75  OPERATOR LICENSE # 5447 WELL TOTAL DEPTH 6060 FEET  OPERATOR: OXY USA, INC PRODUCTION CSG: SIZE " FEET
OPERATOR: OXY USA, INC PRODUCTION CSG: SIZE " FEET
NAME AND BOX 2528 SURFACE CASING: SIZE 85%" @ 1720' WITH SX
ADDRESS LIBERAL, KS 67905-2528
ABANDONED OIL WELLGAS WELLINPUT WELLSWD WELLD/AX
OTHER WELL AS HEREINAFTER INDICATED
PLUGGING CONTRACTOR <u>DUKE DRILLING CO., INC.</u> LICENSE NUMBER <u>5929</u>
ADDRESS 100 S MAIN, SUITE 410 WICHITA, KS 67202-3737
COMPANY TO PLUG AT: HOUR: 8:00 PM DAY: 23 MONTH: 06 YEAR: 2000
PLUGGING PROPOSAL RECEIVED FROM <u>CAL WILEY</u>
(COMPANY NAME) DUKE DRILLING (PHONE) 316-267-1331
WERE:
1ST PLUG AT 3100' WITH 100 SX CEMENT. 2ND PLUG AT 1750' WITH 50 SX CEMENT.
3RD PLUG AT 600' WITH 40 SX CEMENT. 4TH PLUG AT 40-0' WITH 10 SX CEMENT.
5TH PLUG TO CIRCULATE RAT HOLE WITH 15 SX CEMENT.
6TH PLUG TO CIRCULATE MOUSE HOLE WITH 10 SX CEMENT.
PLUGGING PROPOSAL RECEIVED BY RICHARD LACEY
PLUGGING OPERATIONS ATTENDED BY AGENT?: ALLPARTNONEX_
OPERATIONS COMPLETED: HOUR: 11:00 PM DAY: 23 MONTH: 06 YEAR: 2000
ACTUAL PLUGGING REPORT LOAD HOLE WITH HEAVY MUD SPOT PLUGS THRU DRILL PIPE
1ST PLUG AT 3100' WITH 100 SX CEMENT. 2ND PLUG AT 1750' WITH 50 SX CEMENT.
3RD PLUG AT 600' WITH 40 SX CEMENT. 4TH PLUG AT 40-0' WITH 10 SX CEMENT.  STATE CORPORATION COMMISSION 5TH PLUG TO CIRCULATE RAT HOLE WITH 15 SX CEMENT.
5TH PLUG TO CIRCULATE RAT HOLE WITH 15 SX CEMENT.
6TH PLUG TO CIRCULATE RAT HOLE WITH 15 SX CEMENT.  6TH PLUG TO CIRCULATE MOUSE HOLE WITH 10 SX CEMENT.  CONSTR.
REMARKS: USED 60/40 POZMIX 6% GEL BY HALLIBURTON Wichita Kansak  (IF ADDITIONAL DESCRIPTION IS PROCESSARY, USE BACK OF THIS FORM.)
I DID NOT OBSERVE THIS BLUGGING. 7/5/OGGNED Authorit W. Lander
TECHNICIAN) FORM CP-2/3