To:		. AP	NUMBER 15-	107 21,		400	
ONSERVAT	PORATION COMMISSION ION DIVISION - PLUGGING SECTION ADO DERBY BUILDING KANSAS 67202	. s/2 <u>s/</u>	200			S, R 38	
TECHNICIA	N'S PLUGGING REPORT	_	3960	teet	from	E section	l ine
Operator	License # 5003	Lei	sse Name_Qui	gg A	Ho	1-33	
Operator: Name& Address	McCoy Petroleum Corporation	Col	unty Stevens			201.50)
	3017 N. Cypress		li Total Depi	h	620	0	fest
	Wichita, KS 67226-4003	Co	nductor Pipe:	Slze_		feet	 _
			rface Casing:			•	
Abandonad	Oll Well Gas Well	K Inpu	t Well	SMD /	Well	D&A	
Other Wel	l as hereinafter indicated					· 	
	ContractorJ.W. Gibson Well Se	ervice Co.	·	Licen	se Num	5866	
	.O. Box 237, Henderson, CO 80640			•		•	
·	to plug at: Hour: 8:30 a.m. Day:		Month:	4		Yaar: 1995	
	proposal received from Tom I						
	name) J.W. Gibson Well Service				4-5		
	name) 3.w. Gibson well Service $\frac{1}{2}$ " at 6199' w/200 sx cement, TOO						
			, iciro ac	6034-42	-open		
	29' w/250 sx cement, TOC 1500'						
lst plug	set CIBP at 5950' with 2 sx cen	nent on to	p, load hole	with m	ud,		
2nd plug	shoot pipe at 1408 and spot 50) sx cemer	ıt, ı				
3rd plug	pump 40 sx cement at 712', 4th	plus pumi	10 sx cemen	<u>t at 40</u>	to -4	1	
	Plugging P	roposal R	Received by	G	lenn B		
						INICIAN)	
Plugging	Operations attended by Agent?:	A1 1	X				
	•	····	Fari		N	one	
Operatio	ns Completed: Hour: 3:45 p.m.Da		- -				
-		y:1	11 Month:	4		Year:19 95	w/mud.
ACTUAL P	ns Completed: Hour: 3:45 p.m.Da	at 5950'	Month:	4		Year:19 95	w/mud.
actual P	ns Completed: Hour: 3:45 p.m.Da	at 5950'	Month:	4		Year:19 95	w/mud.
2nd plug 3rd plug	ns Completed: Hour: 3:45 p.m.Da LUGGING REPORT 1st plug set:CIBP shot pipe at 1408 and spotted	at 5950' 50 sx cen	Month:	4		Year:19 95 Loadedohole	
2nd plug 3rd plug	LUGGING REPORT 1st plug set:CIBP shot pipe at 1408 and spotted pumped 40 sx cement at 712;	at 5950' 50 sx cen	Month:	4		Year:19 95	
ACTUAL P 2nd plug 3rd plug	LUGGING REPORT 1st plug set:CIBP shot pipe at 1408 and spotted pumped 40 sx cement at 712;	at 5950' 50 sx cen	Month:	4		Year:19 95 Loaded hole	
ACTUAL P 2nd plug 3rd plug 4th plug	LUGGING REPORT 1st plug set:CIBP shot pipe at 1408 and spotted pumped 40 sx cement at 712; pumped 10 sx cement at 40 to -4	at 5950' 50 sx cen	Month: with 2 sx center,	4 ment on	top.	Year:19 95 Loaded hole	95
2nd plug 3rd plug 4th plug	LUGGING REPORT 1st plug set:CIBP shot pipe at 1408' and spotted pumped 40 sx cement at 712'; pumped 10 sx cement at 40 to -4	at 5950' 50 sx cen 4'.	with 2 sx cement,	of $5\frac{1}{2}$ "	top.	Year:19 95 Loaded hole 44-/4- OTATE CONSECUENCES	
ACTUAL P 2nd plug 3rd plug 4th plug Remarks:	Used common cement by J.W. Gill additional description	at 5950' 50 sx cen 4'.	with 2 sx cement,	of 5½"	top.	Year:19 95 Loaded hole 44-/4- OTATE CONSECUENCES	95
2nd plug 3rd plug 4th plug Remarks:	LUGGING REPORT 1st plug set:CIBP shot pipe at 1408' and spotted pumped 40 sx cement at 712'; pumped 10 sx cement at 40 to -4	at 5950' 50 sx cen 4'.	with 2 sx cement,	of 5½"	top.	Year:19 95 Loaded hole 44-/4- OTATE CONSECUENCES	95