

KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

R

TO: Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Sumner

Location: SW NW NW Sec. 12 Twp. 34 Rge. 4 (W)

Name of Field: \_\_\_\_\_ Total Depth: 4741

I have this date completed supervision of plugging of:

Lease Name: C. Sears Well No. 1

Operator's Full Name: General Drilling Co.

Complete Address: Box 489, Tulsa Okla

Plugging Contractor: Operator & Halliburton Cement Co.

Address: \_\_\_\_\_ License No. K-103

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 10 AM Day 2 Month 3 Year 59

The above well was plugged as follows:

Filled hole with 44 viscosity rating mud to 240' where set Hawco plug and had Halliburton Cement Co. pump 30 sacks mixed cement thru drill pipe to bridge. Filled hole with mud to 40' where set Hawco plug and had Halliburton pump cement to 3' below surface ground level where cut off surface.

RECEIVED  
STATE CORPORATION COMMISSION

MAR 11 1959

CONSERVATION DIVISION  
Wichita, Kansas

Jewel M. Ogden  
Conservation Division Agent

Reviewed: G  
Field Supervisor

Remarks:

PLUGGING  
FILE SEC. 12 T. 34 R. 4W  
BOOK PAGE 24 LINE 25