

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Gulf Oil Corporation Address Box 661, Tulsa, Oklahoma  
(Applicant)

Lease (Farm Name) C. Pyle Well No. 2

Well Location 2310' SNL Sec. 16 Twp. 29S Rge. (E) - (W) 16

County Kiowa Field Name (if any) Pyle

Total Depth 4740' Oil  Gas  Dry Hole

Was well log filed with application? Yes If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin At Once

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner P. M. Smith

Address 219 1/2 S. Main, Pratt, Kansas

Plugging Contractor Forbes Casing Pulling Co.

Plugging Contractor's License No. \_\_\_\_\_

Address Box 221, Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

W. H. Duley Address Box 225, Great Bend, Kansas

and payment will be guaranteed by applicant.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
Wichita, Kansas

6-19-1956

*W. H. Duley*

Area Superintendent of Production  
Applicant or Acting Agent

Date 6-18-56

PLUGGING  
FILE SEC 16 T. 29 R. 16W  
BOOK PAGE 72 LINE 18



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

June 19, 1956

Well No. 2  
Lease Pyle  
Description CSW SW NE 16-29-16W  
County Kiowa  
File No. 72-18

Gulf Oil Corporation  
Box 225  
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By

A handwritten signature in cursive script that reads "S. S. Greider".

S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor