FORM - CP-2 Rev. 9-8-64

State of Kansas

WM. H. AVERY
WILLIAM I. MITCHELL
JAMES O. GREENLEAF
HARRY G. WILES
RAYMOND B. HARVEY
E. EDWARD JOHNSON
Gon. Counsel

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
500 Insurance Bldg. 212 N. Market
WICHITA, KANSAS 67202

VERBAL PERMIT FORM (To Be Filed By Plugging Agent)

JUL 3 1967

CONNECTION DIVISION

7-3-6-7

J. P. Roberts Administrator 500 Insurance Building Wichita 2, Kansas

Intent to Drill, filed June 6, 1967.

Dear Sir:

MrCurtisguarantees payment of the plugging fee. Operator's full Name:Grahem-Michaelis Drilling, Inc. Complete Address:211 N. Broadway, Wichita, Knasas 67202 Lease Name:Rudd	Mr. Tom Curtis of Graham-Michaelis Drlg has this
Operator's full Name: Graham-Michaelis Drilling, Inc. Complete Address: 211 N. Broadway, Wichita, Knasas 67202 Lease Name: Rudd Well No. #1-14 Location: C NW SE Sec.14 Twp. 29 Rge.20 (E) (W) W County Kiowa Total Depth 5216' Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	date requested permission to plug the following described well:
Operator's full Name: Graham-Michaelis Drilling, Inc. Complete Address: 211 N. Broadway, Wichita, Knasas 67202 Lease Name: Rudd Well No. #1-14 Location: C NW SE Sec.14 Twp. 29 Rge.20 (E) (W) W County Kiowa Total Depth 5216' Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	Mr. Curtis guarantees payment of the plugging fee.
Lease Name: Rudd Well No. #1-14 Location: C NW SE Sec.14 Twp. 29 Rge.20 (E) (W) W County Kiowa Total Depth 5216' Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	
Location: C NW SE Sec.14 Twp. 29 Rge.20 (E) (W) W County Kiowa Total Depth 5216' Oil Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', lst cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	Complete Address: 211 N. Broadway, Wichita, Knasas 67202
Total Depth 5216' 011 Well Gas Well Input Well SWD Well D & A X Lost Hole Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', lst cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	Lease Name: Rudd Well No. #1-14
Gas WellInput WellSWD WellD & A_X_Lost Hole	Location: C NW SE Sec.14 Twp. 29 Rge.20 (E) (W) W
Mr. Curtis was instructed to plug the well as follows: 566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with ½ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	County Kiowa Total Depth 5216 011 Well
566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with $\frac{1}{2}$ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	Gas WellInput WellSWD WellD & A_X_Lost Hole
566' of 8 5/8" surface pipe, cement circulated with 325 sacks. Fill hole with drilling mud to 400', 1st cementing plug, bridge with $\frac{1}{2}$ sack of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40',	Mr. Curtis was instructed to plug the well as follows:
of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40,	
	hole with drilling mud to 400', 1st cementing plug, bridge with 2 sack
	of hulls, and cement with 25 sacks. Fill hole with drilling mud to 40,
and cementing plug, bridge with a sack of hulls, and cement with 10	2nd cementing plug, bridge with $\frac{1}{2}$ sack of hulls, and cement with 10
sacks to base of cellar. Bridge and cement rat hole with 2 sacks.	sacks to base of cellar. Bridge and cement rat hole with 2 sacks.

Very truly yours,

Conservation Division Agent