| | 1 | | | | | Form CP- | |
|---|--|--|--|--|--|---------------------|--|
| Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division | | WE | LL PLU | GGING RI | ECORD | | |
| Conservation Division State Corporation Commission 212 No. Market Wichita, Kansas 67202 NORTH | t` | Kingman | County | v. Sec. 14 T | 29 Rge. | W(W)(W | |
| | Location as "N | Location as "NE/CNW%SW%" or footage from lines | | | | | |
| | - Lease Owner | Lease Owner Mueller A#1 Well No. | | | | | |
| | Office Address. | Wichita, | Kansas | | | | |
| | 1 | Character of Well (completed as Oil, Gas or Dry Hole) | | | | | |
| | | Date well completed | | | | | |
| | | Application for plugging filed 19 Application for plugging approved 19 | | | | | |
| | Application to | Application for plugging approved 19 Plugging commenced 6/23/70 19 | | | | | |
| i l i | Plugging comp | | 26/70 | | | 19 | |
| | Reason for aba | andonment of well | | formation | leplated. | | |
| | If a producing | well is abandone | d, date of las | st production | · · · · · · | 19 | |
| Locate well correctly on above Section Plat | | on obtained from | | | | re plugging was com | |
| iame of Conservation Agent who supe | ervised plugging of th | nis well Bibe | rstein | | | 1.105 | |
| roducing formation | | Depth to top | Bottom | | Total Depth of V | Well 4497 Fee | |
| how depth and thickness of all water, | , oil and gas formatio | ons. | | | | | |
| OIL, CAS OR WATER RECORD | OS | | | | C | ASING RECORD | |
| FORMATION | CONTENT | FROM | TØ | SIZE | PUT IN | PULLED DUT | |
| | | | - | <u>8–5/8</u> | 238 | none | |
| | | | | 5½11 | 4471 | 38051 | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| feet for each plug se | nent or other plugs wet. | vere used, state the | e character of | f same and dept | h placed, from Mixed | | |
| checked hole to and dumped 5 se | nent or other plugs weet. o 4497', ran sacks of cemen | sand to 4460 | e character of | f same and dept | Mixed | | |
| checked hole to and dumped 5 sepulled \$200 42 | nent or other plugs wet. o 4497', ran sacks of cemen joints. Well | sand to 4460 | o' and du | same and dept ag cellar. ot pipe at in, had wa | Mixed 2784 | feet | |
| Checked hole to and dumped 5 sa pulled \$20 42 truck pump in, | nent or other plugs weet. o 4497', ran sacks of cemenjoints. Well | sand to 4460 t, loaded ho blew in, sh | o character of o and du ole. Sho out well s weight | s cellar. t pipe at in, had wa mud and 1 | Mixed 2784' ater 3 sacks sal | feet | |
| checked hole to and dumped 5 sa pulled \$20 42 truck pump in, gel. Pulled re | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | g cellar. ot pipe at in, had wa mud and 1 | Mixed 2784' ater 3 sacks sal | feet | |
| Checked hole to and dumped 5 so pulled 120 42 truck pump in, | nent or other plugs weet. o 4497', ran sacks of cemen joints. Well had Globe purest of pipe. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | g cellar. ot pipe at in, had wa mud and 1 | Mixed 2784' ater 3 sacks sal | feet | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | g cellar. ot pipe at in, had wa mud and 1 | Mixed 2784' ater 3 sacks sal | feet | |
| Checked hole to and dumped 5 so pulled \$20 42 truck pump in, gel. Pulled re and dumped 25 so and dumped 25 so pulled re and dumped 25 so | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | g cellar. ot pipe at in, had wa mud and 1)', set 10 10' rock | Mixed 2784' ater 3 sacks sal rock brid bridge and | t | |
| Checked hole to and dumped 5 sa pulled \$20 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | g cellar. ot pipe at in, had wa mud and 1), set 10 10' rock | Mixed 2784' ater Sacks sal' rock brid bridge and | t ge | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | ag cellar. t pipe at in, had wa mud and l ', set 10 10' rock | Mixed 2784' ater 3 sacks sal rock brid bridge and | t ge | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | ag cellar. t pipe at in, had wa mud and l ', set 10 10' rock | Mixed 3784' ater 3 sacks sal rock brid bridge and ECEIVED REGRATION COM | t ge MISSION | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | ag cellar. t pipe at in, had wa mud and l ', set 10 10' rock | Mixed 3784' ater 3 sacks sal rock brid bridge and ECEIVED REGRATION COM | t ge MISSION | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui | o' and du ole. Sho out well s weight d to 200 | ag cellar. t pipe at in, had wa mud and l ', set 10 10' rock | Mixed 2784' ater 3 sacks sal rock brid bridge and | t ge MISSION | |
| Checked hole to and dumped 5 sa pulled 120 42 truck pump in, gel. Pulled re and dumped 25 sand dumped 25 sand dumped 35 sand d | nent or other plugs weet. 0 4497', ran sacks of cemen joints. Well had Globe purest of pipe. sacks of cemen f cement. | sand to 4460 t, loaded ho blew in, sh mps 32 sacks Bailed flui nt. Mudded | e character of and duple. Shout well weight do 200 to 40°, | reg cellar. ot pipe at in, had wa mud and l of rock R STATE CO | Mixed 3784' ater 3 sacks sal rock brid bridge and ECEIVED REGRATION COM | t ge MISSION | |

SUBSCRIBED AND SWORN TO BESTE me this. 2/15/71

Minimum and the second

well, being first duly sworn of path, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.

(Signature).

(Address)

CHASE, KANSAS

June

_(employee of owner) or (owner or operator) of the above-described

70