_		/ 2 ~		d -
To:	1 051451	-API. NUMBER 15-151-21,671-60-00 182 R		
	PORATION COMMISSION ION DIVISION - PLUGGING SECTION App	C N/2 SW NW	21 28	
200 COLOR	WAN DEVOT BUILDING			-
WICHIȚA,	KANSAS 67202		feet from S sect	ion line
TECHNICIA	N'S PLUGGING REPORT	4520 	feet from E sect	ion line
Operator	License # 5893	Lease Name Bake	r Well # 1	
Name&	Pratt Well Service, Inc.			
	P.O. Box 847		4930	
	Pratt, KS 67124		Sizefeet_	
	•		Size 8 5/8 feet 47	
Abandoned	Oll Wall X Gas Wall	-		· · · · · · · · · · · · · · · · · · ·
	Oll Well X Gas Well	bu: #611	SWD WellD	&A
	Pratt Well Service,	Inc.		
Plugging	Contractor		License Number 589	
	P.O. Box 847, Pratt, KS 67124			·
Company t	o plug at: Hour: 9:30 a.m. Day:	25 Month:	6 Year:19	91 .
	proposal received from Bruce Wag			
(company	name) Pratt Well Service, Inc.		(nhone) 316-67	2-5901
	" at 4930', Perfs at 4832-4614'	· · · · · · · · · · · · · · · · · · ·	(pilot(e)	
	sand back to 4565' and dump 5 sx cen	ment on top of san	d through bailer,	
2nd plug	pump 3 sx hulls, 10 sx gel, 50 sx co	ement 10 sy del	l sy hulls release	8 5/8"
2114 17245	pump 5 br nurrb, to br ger, 50 br e	emone, to on bear,	z on marris, rondado	5 5, 5
wiper pl	ug and pump 100 sx cement.	· · · · · · · · · · · · · · · · · · ·		
wiper pl				·································
wiper p1		al Received by	Case Morris	· · · · · · · · · · · · · · · · · · ·
· · · · · · · · · · · · · · · · · · ·	ug and pump 100 sx cement. Plugging Propose		Case Morris (TECHNICIAN)	
Plugging (ng and pump 100 sx cement. Plugging Propose Operations attended by Agent?: All	X Part_	(TECHNICIAN) None	
Plugging (ug and pump 100 sx cement. Plugging Propose	X Part_	(TECHNICIAN) None	91
Plugging (Operations	ng and pump 100 sx cement. Plugging Propose Operations attended by Agent?: All	X Part 25 Month:	(TECHNICIAN) None 6 Year:19	
Plugging (Operations ACTUAL PLI	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m Day:	X Part 25 Month:	(TECHNICIAN) None 6 Year:19	
Plugging (Operations ACTUAL PLU through	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m Day:	X Part	(TECHNICIAN) None 6 Year:19 5 sx cement on top	of sand
Plugging (Operations ACTUAL PLU through	Plugging Propositions attended by Agent?: All Completed: Hour: 10:30 a.m. Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 50	X Part 25 Month: 0 4565' and dumped 0 sx cement, 10 sx	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls	of sand
Plugging (Operations ACTUAL PLU through 1 2nd plug released	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 5 8 5/8" wiper plug and pumped 100 sx	X Part 25 Month: o 4565' and dumped 0 sx cement, 10 sx cement.	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls	of sand
Plugging (Operations ACTUAL PLU through 1 2nd plug released	Plugging Propositions attended by Agent?: All Completed: Hour: 10:30 a.m. Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 50	X Part 25 Month: o 4565' and dumped 0 sx cement, 10 sx cement.	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls STATE CORP	of sand CEIVED- RATION COMMIS
Plugging (Operations ACTUAL PLU through 2nd plug released Maximum	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 5: 8 5/8" wiper plug and pumped 100 sx pressure 500 psi and shut in 100 psi	X Part 25 Month: 0 4565' and dumped 0 sx cement, 10 sx cement.	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls STATE CORM	CEIVED- PRATION COMMIS O 1 1991 O 1 1991 VATION DIVISION
Plugging (Operations ACTUAL PLU through 2nd plug released Maximum	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m. Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 50 8 5/8" wiper plug and pumped 100 sx pressure 500 psi and shut in 100 psi Used 60/40 Pozmix 6% gel by Allied.	X Part 25 Month: o 4565' and dumped 0 sx cement, 10 sx cement. Recovered 2505' o	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls STATE CORM Character f 5½" casing. Wid	CEIVED- PRATION COMMIS 0 1 1991
Plugging (Operations ACTUAL PLU through 2nd plug released Maximum	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m. Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 5 8 5/8" wiper plug and pumped 100 sx pressure 500 psi and shut in 100 psi Used 60/40 Pozmix 6% gel by Allied.	X Part 25 Month: o 4565' and dumped 0 sx cement, 10 sx cement. Recovered 2505' o	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls STATE CORM Character f 5½" casing. Wid	CEIVED- PRATION COMMIS O 1 1991
Plugging (Operations ACTUAL PLU through 2nd plug released Maximum	Plugging Propose Operations attended by Agent?: All s Completed: Hour: 10:30 a.m. Day: UGGING REPORT 1st plug sanded back to bailer. pumped 300 lbs. hulls, 10 sx gel, 50 8 5/8" wiper plug and pumped 100 sx pressure 500 psi and shut in 100 psi Used 60/40 Pozmix 6% gel by Allied.	X Part 25 Month: o 4565' and dumped 0 sx cement, 10 sx cement. Recovered 2505' o	(TECHNICIAN) None 6 Year:19 5 sx cement on top gel, 100 lbs. hulls STATE CORM Character f 5½" casing. Wide of this form.)	CEIVED- PRATION COMMIS O 1 1991 O 1 1991 VATION DIVISION