Wichita, Kansas

1	FILEVI	N WELL L	OG AS	REQU	TRED:		1			
Show all important : cluding depth intervo	zones of porosity e	nd contents th	nereaf; care	d Inter	vats, and all			SHOW GEOLOG OR OTHER DI	SCRIPTIVE	INFORMA
A TORMATI	OH DESCRIPTION,				TOP		оттом	HAME		DCPT
LOG TOPS:	4:00									
1	427	, ,			}	ŀ				
Heebner Toronto	437- 439		-1774 - 1 797		}					
Lansing	452		-1926		ł	1				
Swope Ø Zone		-	-		[ĺ				
Base Kansas	_		-2399		İ	- }	i			
Marmaton Altamont	501		2419		ł	ł	l			
Pawnee	505 509		-2453 -2498		ł					
Cherokee	514		2544		1	- 1	- 1			
Morror Shale	525	2' -	2652			- 1			Í	
Mississippi	5288	3' -	2688			-				
DST #1 5240'					İ	}				
	/45/60				ļ	- {			ł	
	60' mud blow throu	ighout			1	1			ł	
ISIP	150 IF	P 107-1	07	IHE	2590	ł	l		1	
FSIP		P 118-1		FHE		ł	ļ			
İ						ł	Į			
	•						Ì			
								AU FROM C	FIEL	D==
							ĺ	6.1		(ED
								AU ~~~	601	1933
				ľ		- [1	THOM C	ONEIL	۱۳.
				- 1		- }	}		· ' -	VENT!
							1		1	
Report of all string	s set — surface,	Size cosing sal				RECORD	(New	or (Used		
		(In O.D.)	Walght 18	*/ 11.] 3.	etting depth	Тура	tement	Sacks	2% Ge	and percer
Surface	12 1/4"	8 5/8"	23#	1.5	505'	Common	n	300	3% CC	
y to the second court of t	and community of the second se	the ordered as	1	- [
Para Talan			 	7						
									<u> </u>	
	LINER RECOR	 D		{}	<u>-</u>		PERFORA	TION RECOR		 -
p, H. Battom, H. Sacks coment					51			e & type Depth interval		
TUBING RECORD					_W/A		 			<u>-</u> _
I/A	etting depth	Packer	et of		N/A		 -			
		ID, FRACT				EEZE REC	ORD			
Amount and kind of material used								Depth interval treated		
/A									 -	
	<u> </u>									
ate of first production	27P4.		method (f	iowing,	pumping, ge	lift, etc.)	·	Crassia	 .	···
ATE OF PRODUCTION OIL						Water	Gravity N/A Gos-oil ratio			
Isposition of gas (vented,	N/A	bb);	1		м	cr N/A	%	bbls. N/		
A	was en leam of to	d)					oration		<u> </u>	CFI