
## KANSAS STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO: Jewel M. Ogden, Director 500 Insurance Building 212 North Market Wichita 2, Kansas



File No.	_County:_	Kiowa	<del></del>	, 	<del></del>		·
Location: C NW NW		Sec. 16	_Twp	27 S R	ge。 <u>16</u>	(E)	(W)_X
Name of Field:			_Total	Depth:	4765		, , , , , , , , , , , , , , , , , , ,
I have this date completed super	vision of	plugging of	:	•			
Lease Name: Warren	4 <b>/</b> ;			Well	No	1	
Operator's Full Name: Hilton Drlg.	. Sun Oil	Co. Tatlock	Oil Co	•		<del></del>	
Complete Address: 925 Patton Ro	oad		<del></del>	4	·····	P. J	· · ·
Plugging Contractor: Hilton Dri	illing			<del></del>		<del></del>	-
Address: 925 Patton Road	f	•	1.	Licen	se No		· .
Oil WellGas Well	Input	Well_	SWD	We11	D	& A X	
Other well as hereafter indicate	d:	<del></del>		, ,			<del> </del>
Was any delay in plugging operat	ions caus	; ed by Conser	vation	Divisio	n Agent?	Yes	No
If yes how long?	· · · · · · · · · · · · · · · · · · ·	Reason:	٠., -	;	· · · · · · · · · · · · · · · · · · ·		<u></u>
	<del></del>	·		). •		<del></del>	· · ·
		*** · · · · · · · · · · · · · · · · · ·	<del>,</del>	· '	·····		
Operation Completed: Hour 2:30 1	P.M. n	3045-	<b>3</b> 0	- Arto - No -		Vac	· 1070
operation completed. Hour 1990		ay 30th	IMOI	ncn May		I'c	1. 1.929.
The above well was plugged as for		ay 30th	Moi	ica May	· .	T (C C)	r <u>. 1959</u>
*	llows:				<i>:</i> .		<u> </u>
The above well was plugged as fo	llows:	c. hulls and	20 Sac	• cement	- Mudded		<u>1959</u>
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	• cement	- Mudded		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	• cement	- Mudded		. 1959
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	cement	- Mudded		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	cement	- Mudded		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	cement	- Mudded		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	cement se of ce	- Mudded llar.  MISSION  DIVISION		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sac	cement	- Mudded llar.  MISSION  DIVISION		
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	c. hulls and	20 Sact to ba	UN 1 7 18	- Mudded llar.  MISSION  DIVISION  DESCRIPTION	-(7-	59
The above well was plugged as for Hole mudded to 330 Ft Plug	llows:	o. hulls and	20 Sac	UN 1 7 18	- Mudded llar.  MISSION  DIVISION	-(7-	59
The above well was plugged as for Hole mydded to 330 Ft Plug to 35 Ft. Set plug \( \frac{1}{4} \) Sac. hull Reviewed: \( \sum_{\text{Nurse Bure}} \)	llows:  set \frac{1}{4} saccells and 10	o. hulls and	20 Sactoba	UN 1 7 19 RVATION ICHIER, Kelling, Kell	- Mudded llar.  MISSION  SSO  ONVISION  Seas	-(7-	59
The above well was plugged as formulation.  Hole midded to 330 Ft Plug to 35 Ft. Set plug 4 Sac. hull.	llows:  set \frac{1}{4} saccells and 10	o. hulls and	20 Sactoba	cement se of ce UN 1719 RVATION ICHIER, Kei	- Mudded llar.  MISSION  SSO  ONVISION  Seas	-(7-	<u>59</u>