STATE CORPORATION OF THE CORPORA	72-0000
TECHNICIAN'S PLUGGING REPORT Operator: License / 9123 Operator: Diamond Shamrock Operator: Diamond Shamrock County Sedgwick Named Box 23 Lunadian, TX Conductor Pipe: Size feet from W/K & Sufface Casing: Size 8 5/8 feet Surface Casing: Size 8 5/8 feet Surface Casing: Size 8 5/8 feet Abandoned Oll Well Gas Well input Well SWD Well Other well as hereinafter indicated Plugging Contractor Kaw Drilling License Number Address Company to plug et: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) Were: 35 sacks at 4150; 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 RECE STATE CONTROLL	
Operator: Diamond Shamrock Operator: Diamond Shamrock Box 23 Lunadian, TX Conductor Pipe: Size Surface Casing: Size 8 5/8 feet Surface Casing: Size 8 5/8 feet Abandoned Oi! Well Other well as hereinafter indicated Plugging Contractor Kaw Drilling License Number Address Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) Were: 35 Sacks at 4150; 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 ONESPWATE Flugging Operations attended by Agent?: All Plugging Operations attended by Agent?: All Plugging Operations attended by Agent?: All Plugging Operations Compileted: Hour: 8:30p.mDay: 10 Month: 10 Year: Plugging Operations attended by Agent?: All Part None Operations Compileted: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' and 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	XXXXXXX 1
Operator: Name 1 Name 2 Address Box 23 Lunadian, TX Conductor Pipe: Size fe Surface Casing: Size 8 5/8 feet Surface Casing: Size 8 5/8 feet Surface Surfac	
Operator: Name 1 Name 2 Address Box 23 Lunadian, TX Conductor Pipe: Size fe Surface Casing: Size 8 5/8 feet Surface Casing: Size 8 5/8 feet Surface Surfac	<u>1</u>
Name& Address Lunadian, TX Conductor Pipe: Size fe Surface Casing: S1ze 8 5/8 feet Surface Casing: S1ze Surface Surf	
Lunadian, TX Conductor Pipe: Size	37.31
Surface Casing: Size 8 5/8 feet Abandoned Oli Weii 6as Weii input Weii 5WD Weii Other well as hereinaffer Indicated Plugging Contractor Kaw Drilling License Number Address Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phono) vere: 35 sacks at 4150; 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 Fat 60-40, 2% gel, 2% cc RECE STATE COMPONAN (CT 1 CONSERVATE Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' at 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc	feet
Other well as hereinafter indicated Plugging Contractor Kaw Drilling License Number Address Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phone) were: 35 sacks at 4150; 25 at 1150'; 35 at 360'; 25 on plug at 60'; 16 rat 60-40, 2% gel, 2% cc RECE STATE COMPONENT CONSERVABLE Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' at 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc	et307
Other well as hereinafter indicated Plugging Contractor Kaw Drilling License Number Address Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phone) were: 35 sacks at 4150; 25 at 1150'; 35 at 360'; 25 on plug at 60'; 16 rat 60-40, 2% gel, 2% cc RECE STATE COMPONENT CONSERVABLE Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' at 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	D&A
Plugging Contractor Kaw Drilling License Number Address Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phone) vere: 35 sacks at 4150;, 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 rat 60-40, 2% gel, 2% cc RECE S(ATE COMPENSATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agont?: Ali Year: None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Company to plug at: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phone) were: 35 sacks at 4150;, 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 rat 60-40, 2% gel, 2% cc RECE STATE COMPANY OCT 1 CONSERVATE Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Year: None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' at 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Company to plug et: Hour: 10:00a.m.Day: 10 Month: 10 Year: Plugging proposal received from Pete Coats (company name) (phone) vere: 35 sacks at 4150;, 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 rat 60-40, 2% gel, 2% cc RECE STATE COMPONATI (C) - 1 S (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Plugging proposal received from Pete Coats (company name)	- 40 84
(company name) (phone) were: 35 sacks at 4150;, 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 rat 60-40, 2% gel, 2% cc RECE STATE CORPORATI CONSERVATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL Plugging REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
were: 35 sacks at 4150;, 25 at 1150'; 35 at 360'; 25 on plug at 60'; 10 rat 60-40, 2% gel, 2% cc RECE STATE CORPORATI CONSERVATIC Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Plugging Proposal Received by Stan Marcotte Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Year: Plugging Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
CONSERVATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (if additional description is necessary, use BACK of this form.)	10 in
CONSERVATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (if additional description is necessary, use BACK of this form.)	CEIVED
CONSERVATION CONSERVATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All	8-1982
CONSERVATION Plugging Proposal Received by Stan Marcotte (TECHNICIA Plugging Operations attended by Agent?: All Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement . Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (if additional description is necessary, use BACK of this form.)	187301
Plugging Proposal Received by Stan Marcottee (TECHNICIA Plugging Operations attended by Agent?: Ali Year: Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' at 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	ATION DIVISION
Plugging Operations attended by Agent?: Ali Part None Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. Pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	CIAN)
Operations Completed: Hour: 8:30p.mDay: 10 Month: 10 Year: ACTUAL PLUGGING REPORT Fill hole with heavy mud. Ran drill pipe to 4150' a 35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	i
35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
35 sacks of cement, pulled pipe to 1150' and spotted 25 sacks of cement. pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (if additional description is necessary, use BACK of this form.)	and spott
pipe to 360' and spotted 35 sacks of cement. Set wood and rubber plug spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	-
spotted 25 sacks of cement. Circulated 10 sacks of cement in the rat ho 60-40, 2% gel, 2%cc Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	
Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.) (If additional description is necessary, use BACK of this form.)	
Remarks: Haliburton Ticket #890693 (If additional description is necessary, use BACK of this form.)	по⊥е
(if additional description is necessary, use BACK of this form.)	
(if additional description is necessary, use BACK of this form.)	
VI Valle City observe this plugging.	
)
10-29-84 Ward Ward (TECHNICHAR)	
10	
40, 4099 VCP	FORM CP-

FORM CP-2/3 Rev.01-84