15-173-01392-0000 · .: 2090008 API NUMBER 15- NA STATE CORPORATION COMMISSION S/2 SESW SEC. 2 , 7 27 S, R 1 CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING feet from N/S section line WICHITA, KANSAS 67202 feet from W/E section line TECHNICIAN'S PLUGGING REPORT Lease Name College \_\_\_ Weil #\_\_\_1\_\_\_ Operator License #\_\_\_\_5463\_\_\_\_ County Sedgwick Operator: \_\_\_\_Samson Resources Name& Well Total Depth 2719 Valley Center, Ks. Address Conductor Pipe: Size 10 3/4 feet 175 Surface Casing: Size\_\_\_7" feet Abandoned Oll Well X \_\_\_\_ Gas Well\_\_\_\_\_ Input Well\_\_\_\_\_ SWD Well\_\_\_\_\_ D&A\_\_\_\_ Other well as hereinafter indicated\_\_\_\_\_ Plugging Contractor Kelso Casing and Pulling License Number 6050 P.O. Box 176, Chase, Ks. Company to plug at: Hour: 11:00p.m. Day: 5 Month: 6 Year:19 8/ Plugging proposal received from Norman Voth (company name) Kelso Casing & Pulling (phone) 398-2457 sand back to 2650' 75 sacks cement - bridge at 250' - bail hole dry and pump redi-mix to surface.\_\_\_\_\_ STATE CORPORATION COMMISSION CONSERVATION DIVISION Wichita, Kansas Plugging Proposal Received by Don Thompson (TECHNICIAN) Plugging Operations attended by Agent?: All\_\_x\_\_\_\_ Part\_\_\_\_\_ None\_\_\_\_\_ Operations Completed: Hour: 11:00p.May: 6 Month: 6 Year:19\_84 ACTUAL PLUGGING REPORT The bottom of the hole was filled with sand to 2650' and 7 sacks of cement were spotted on top of sand through the bailer. The 7' long string was stuck and was unable to pull. The top was plugged with 175 sacks of class "A" cempt, 2%cc. 5% gilsonite. Instant shut in pressure 200 1b. United Cement ticket #7583 175 sacks: 5% gilson; (If additional description is necessary, use BACK of this form.)

INV. NO. 3/4/

Signed Dand (TECHNIC PAN)

FORM CP-2/3 Rev.01-84