STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

File One Copy
Fleming & Woodman & Frank A. Oyster, et al
Lease Owner Address 921 Union National Bank Bldg. (Applicant) Wichita, Kansas
(Applicant) Wichita, Kansas Lease (Farm Name) Walty Well No. 1
Lease (Farm Mante) Walty well No. I
Well Location NE-NE-SW Sec. 5 Twp278 Rge. 4W(E)-(W)
County Sedgwick Field Name (if any)
Total Depth 4087' Oil Gas Dry Hole X
Was well log filed with application? yes . If not, explain:
Date and hour plugging is desired to begin 11:00 P.M. 5-18-55
Plugging of the well will be done in accordance with the Rules and
Regulations of the State Corporation Commission, or with the approval
of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary)
(obe an addational brooks at moore by)
Name of the person on the lease in charge of well for owner
D. E. Elliot Address Great Bend, Kansas
Name of Plugging Contractor Fleming & Woodman Drilling Co.
Address Box 536, Great Bend, Kansas
Invoice covering assessment for plugging this well should be sent to
Fleming & Woodman Drlg. CoAddress Box 536, Great Bend, Kans.
and payment will be guaranteed by applicant.
GING MAY 201955 MAY 201955 Applicant or Acting Agent

Date May 19, 1955

COMSERVATION DIVISION
Wichite, Kanses
5-20-55



STATE OF KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA 2, KANSAS
May 20, 1955
211 N. Broadway

Well No. 1 Lease Walty

Description NE NE SW 5-27-LW

County Sedgwick File No. 120-9

Fleming & Woodman Drilling Co. et al. Box 536 Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkee, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION CONSERVATION DIVISION

J. P. ROBERTS

cc: District Plugging Supervisor