4-<u>020121</u>

	API Number: 15-009-15,571-0000
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING	NW CD NW /4 CDC 22 20 C 12 W
130 SOUTH MARKET, SUITE 2078	NW SE NW /4 SEC. 22 ,20 S, 12 W 3630 feet from S section line
WICHITA, KANSAS 67202	3630 feet from E section line
	reec from a section fine
Operator license# 5920 $4/12$	Lease: Steckel Well # A-5
Operator: TePe Oil & Gas	County: Barton /// 70
Address: P.O. Box 522	Well total depthfeet
Canton, Kansas 67428	Conductor Pipe: 0 inch @ 0 feet
	Surface pipe 8 5/8 Inch @ 230 feet
	
Aband. oil well_x, Gas well, Input well,	SWD, D & A
Plugging contractor: <u>Mike's Testing & Salvag</u>	e, Inc. License#31529
Address: P.O. Box 467 - Chase, Kansas 67524	
Company to plug at: Hour: 8:30 A.M.Day: 12 Mont	h: <u>April</u> Year: 2000
Plugging proposal received from: <u>Monte Andre</u>	ws
Company: Mike's Testing & Salvage, Inc.	Phone: 316-938-2943
Were: Ordered out 250 sxs 60/40 pozmix - 10% ge	1 - 400# hulls.
Prod Perfs at 3293' - 3303'; 3375' - 3385	1. 34101 - 34121 REUEIVEU
Cast Iron Bridge Plug at 3405'.	
Spud 02-02-57.	
Shot casing off at 2010'.	APR 1 4 2000
	AFD 14 2000
	DONESPRATION DIVISION
	DOMESTAN DIVISION DIVISION DIVISION
Plugging Proposal Received by: Herb Deines	DOMESERVATION DIVISION DIVISION
	DOMESERVATION DIVISION DIVISION
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X	nonservator juvisko: Wichita Kansas], Part[], None[]
Plugging Proposal Received by: Herb Deines	nonservator juvisko: Wichita Kansas], Part[], None[]
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X	nonservator juvisko: Wichita Kansas], Part[], None[]
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X Completed: Hour: <u>11:30 A.M.</u> , Day: <u>12</u> Mon	nowservation on the winter Kanser Part[], None[] th: April , Year: 2000
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X Completed: Hour: <u>11:30 A.M.</u> , Day: <u>12</u> Mon Actual plugging report: <u>8 5/8" set at 230' w/22</u>	nowservation on the winter Kanser Part[], None[] th: April , Year: 2000
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X Completed: Hour: <u>11:30 A.M.</u> , Day: <u>12</u> Mon Actual plugging report: <u>8 5/8" set at 230' w/22 Shot casing off at 2010'.</u>	
Plugging Proposal Received by: <u>Herb Deines</u> Plugging operations attended by agent? All[X Completed: Hour: <u>11:30 A.M.</u> , Day: <u>12</u> Mon Actual plugging report: <u>8 5/8" set at 230' w/22</u>	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by: Herb Deines Plugging operations attended by agent? All[X Completed: Hour: 11:30 A.M., Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing out of hole. Topped off with 50	Part[], None[] th: April , Year: 2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs.
Plugging Proposal Received by:	newservation of the winter Manser], Part[], None[] th:, Year:2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ad cement with 80 sxs. sxs cement.
Plugging Proposal Received by:Herb Deines Plugging operations attended by agent? All[X Completed: Hour:1:30 A.M, Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate Pulled casing out of hole. Topped off with 50 Remarks:United Cementing and Acid Company. Condition of casing(in hole): GOOD_X_BAD	nowservation physich: Wighter Manser], Part[], None[] th:, Year:2000 5 sxs. cement. 5 %" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs. sxs cement. Anhy.plug: YESXNO
Plugging Proposal Received by:	Part[], None[] th:April, Year:2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs. sxs cement. Anhy.plug: YESX NO Dakota plug: YESX NO
Plugging Proposal Received by:Herb Deines Plugging operations attended by agent? All[X Completed: Hour:1:30 A.M, Day:12 Mon Actual plugging report: 8 5/8" set at 230' w/22 Shot casing off at 2010'. Pulled cassing to 1450' - tied onto and pumped Pulled casing to 650' - tied onto and circulate Pulled casing out of hole. Topped off with 50 Remarks:United Cementing and Acid Company. Condition of casing(in hole): GOOD_X_BAD	Part[], None[] th:April, Year:2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ad cement with 80 sxs. sxs cement. Anhy.plug: YESX NO Dakota plug: YESX NO
Plugging Proposal Received by:	######################################
Plugging Proposal Received by:	Part[], None[] th:April, Year:2000 5 sxs. cement. 5 ½" set at 3437' w/125 sxs. 100 sxs cement with 300# hulls. ed cement with 80 sxs. sxs cement. Anhy.plug: YESX NO Dakota plug: YESX NO