

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Tennessee Gas Transmission Co., Address P.O. Box 163 Great Bend Kansas
(Applicant)

Lease (Farm Name) M.A. Richardson Well No. 1

Well Location NE NE NE Sec. 22 Twp. 27S Rge. (E) (W) 10

County Kingman Field Name (if any) Artesian Valley

Total Depth 4323 Oil _____ Gas _____ Dry Hole (SWDW)

Was well log filed with application? No If not, explain: _____

Not available - will file as soon as available.

Date and hour plugging is desired to begin July 10 1957

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Glen E. Armour Address P.O. Box 163 Great Bend Kansas

Plugging Contractor West Supply Company

Plugging Contractor's License No. 14

Address Chase Kansas

Invoice covering assessment for plugging this well should be sent to _____

Tennessee Gas Transmission Company Address P.O. Box 163 Great Bend Kansas

and payment will be guaranteed by applicant.

STATE CORPORATION COMMISSION

7-9-57 JUL 9 - 1957

CONSERVATION DIVISION
WICHITA, KANSAS

Glen E. Armour
Applicant or Acting Agent

Date July 6 1957

PLUGGING
FILE SEC. 32 T. 27R 10W
BOOK PAGE 25 LINE 35



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

July 9, 1957

Well No.	1
Lease	M. A. Richardson
Description	NE NE NE 22-27-10W
County	Kingman
File No.	25-35

Tennessee Gas Transmission Co.
P. O. Box 163
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor