TIME CILIE	$\frac{1}{040646}$	API NUMBER 15- 185-22,809-0000	1
CONSERVAT	PORATION COMMISSION ION DIVISION - PLUGGING SECTION		W/8
	ADO DERBY BUILDING Kansas 67202	4950 feet from S section	enli
TECHNICIA	N'S PLUGGING REPORT	1155 feet from E section (	
Operator	License #_ 5822	Lease Name Nelson Well 4 Al	
Operator: Name&	VAL Energy, Inc.	County Stafford	
	P.O. Box 322	Well Total Depth 4155 135.03	feat
	Haysville, KS 67060	Conductor Pipe: Sizefeet	
		Surface Casing: Size 10 3/4 feet 244	
handonad	Oli Well v Gas Well	Input Well SWD Well D&A	
	as hereinafter indicated		
	<del></del>		
		License Number 5822	
	P.O. Box 322, Haysville, KS 6		
		: 15 Month: 4 Year: 19 92	
Plugging	proposal received from Joe Sta	llard	
(company	Neme) VAL Energy, Inc.	(phone) 316-522-156	0
	•	BTD 4152', Perfs at 3938-41, 3949-52, 3966-74;	
	et CIRP at 3550' and dump 2 sx	3588 - 92 - 3608 - 10 - 3714 - 161	
2nd plug p	ump down 10 3/4" surface pipe w	ith 300 lbs. hulls, 10 sx gel, 50 sx cement, 10	sx 2
		ith 300 lbs. hulls, 10 sx gel, 50 sx cement, 10	sx e
	ump down 10 3/4" surface pipe w		sx g
	ulls, release 10 3/4" wîper plu	g and pump 150 sx cement.	sx g
	ulls, release 10 3/4" wîper plu		sx g
100 lbs. h	ulls, release 10 3/4" wîper plu	g and pump 150 sx cement.  roposal Received by Steve Pfeifer  (TECHNICIAN)	sx g
100 lbs. h	ulls, release 10 3/4" wiper plug	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part NoneX	sx g
Plugging Operation	Plugging Poperations attended by Agent?:  S Completed: Hour: 9:25 a.m. Day	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part NoneX	
Plugging Operation	Piugging Po Operations attended by Agent1: s Completed: Hour: 9:25 a.m.Day	g and pump 150 sx cement.  Foposal Received by Steve Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550 and dumped 2 sx cement on top through 1	
Plugging Operation ACTUAL PL	Plugging Poperations attended by Agent1:  S Completed: Hour: 9:25 a.m.Daw  UGGING REPORT 1st plug set CIBP  umped down 10 3/4" surface pipe	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550' and dumped 2 sx cement on top through 1  with 300 lbs. hulls, 10 sx gel, 50 sx cement,	
Plugging Operation ACTUAL PL 2nd plug pu	Piugging Pa Operations attended by Agent1: s Completed: Hour: 9:25 a.m.Day ugging REPORT 1st plug set CIBP umped down 10 3/4" surface pipe	g and pump 150 sx cement.  FOR STEVE Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550' and dumped 2 sx cement on top through 1  with 300 lbs. hulls, 10 sx gel, 50 sx cement,  4" wiper plug and pumped 150 sx cement.	
Plugging Operation ACTUAL PL 2nd plug pu	Plugging Poperations attended by Agent1:  S Completed: Hour: 9:25 a.m.Daw  UGGING REPORT 1st plug set CIBP  umped down 10 3/4" surface pipe	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550' and dumped 2 sx cement on top through 1  with 300 lbs. hulls, 10 sx gel, 50 sx cement,  4" wiper plug and pumped 150 sx cement.  si.  RECEIVED	bail
Plugging Operation ACTUAL PL 2nd plug pu	Piugging Pa Operations attended by Agent1: s Completed: Hour: 9:25 a.m.Day ugging REPORT 1st plug set CIBP umped down 10 3/4" surface pipe	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550' and dumped 2 sx cement on top through 1  with 300 lbs. hulls, 10 sx gel, 50 sx cement,  4" wiper plug and pumped 150 sx cement.  si.	bail
Plugging Operation ACTUAL PL 2nd plug pt 10 sx gel, Maximum pro	Plugging Poperations attended by Agent?:  s Completed: Hour: 9:25 a.m.Daw  ugging REPORT 1st plug set CIBP  umped down 10 3/4" surface pipe  100 1bs. hulls, released 10 3/4  essure 200 psi and shut in 50 ps	g and pump 150 sx cement.  roposal Received by Steve Pfeifer (TECHNICIAN)  All Part None X  y: 15 Month: 4 Year:19 92  at 3550' and dumped 2 sx cement on top through 1  with 300 lbs. hulls, 10 sx gel, 50 sx cement,  4" wiper plug and pumped 150 sx cement.  si.  RECEIVED STATE CORPORATION COMMISSI	bail
Plugging Operation ACTUAL PL 2nd plug pt 10 sx gel, Maximum pro	Plugging Poperations attended by Agent1:  s Completed: Hour: 9:25 a.m. Day  ugging Report 1st plug set CIBP  umped down 10 3/4" surface pipe  100 1bs. hulls, released 10 3/4  essure 200 psi and shut in 50 psi  Used 60/40 Pozmix 6% gel by Ali	g and pump 150 sx cement.  Steve Pfeifer  (TECHNICIAN)  AllPartNoneX  y:15	bail
Plugging Operation ACTUAL PL 2nd plug pt 10 sx gel, Maximum pro	Plugging Populations attended by Agent?:  S Completed: Hour: 9:25 a.m. Daw  UGGING REPORT 1st plug set CIBP  umped down 10 3/4" surface pipe  100 1bs. hulls, released 10 3/4  essure 200 psi and shut in 50 ps  Used 60/40 Pozmix 6% gel by Al.  (if additional description	g and pump 150 sx cement.    Steve Pfeifer (TECHNICIAN)	bail
Plugging Operation ACTUAL PL 2nd plug pu 10 sx gel, Maximum pro	Plugging Poperations attended by Agent1:  s Completed: Hour: 9:25 a.m. Day  ugging Report 1st plug set CIBP  umped down 10 3/4" surface pipe  100 1bs. hulls, released 10 3/4  essure 200 psi and shut in 50 psi  Used 60/40 Pozmix 6% gel by Ali	g and pump 150 sx cement.    Steve Pfeifer	bail
Plugging Operation ACTUAL PL 2nd plug pt 10 sx gel, Maximum pro	Plugging Populations attended by Agent?:  S Completed: Hour: 9:25 a.m. Daw  UGGING REPORT 1st plug set CIBP  umped down 10 3/4" surface pipe  100 1bs. hulls, released 10 3/4  essure 200 psi and shut in 50 ps  Used 60/40 Pozmix 6% gel by Al.  (if additional description	g and pump 150 sx cement.    Steve Pfeifer (TECHNICIAN)	bail