To:	1120703 . 4-	-/6, API NUMBER 15- 047-20,518-0000	
CONSERVAT	PORATION COMMISSION ION DIVISION - PLUGGING SECTION	ON Irr. Sec. NW , SEC. 3 , T. 26 s, R! 16 W/F	
200 GOLOK	ADO DERBY BUILDING Kansas 67202	3530 feet from NXX section line	
TECHNICIAN'S PLUGGING REPORT 330 feet from WEX section lin			
Operator License # 5992 Lease Name Southwest College 1			
	Patton Oil Company	County Edwards 143.97	
Nam e č Address	672 W. 4th St.	Well Total Depth 4430 feet	
	Hoisington, KS 67544	Conductor Pipe: Sizefeet	
		Surface Casing: Size 8 5/8 feet 435	
benobned	011 WellX Gas Well	Input WellSWD WellD&A	
	1 as hereinafter indicated		
Plugging Contractor Kelso Casing Pulling, Inc. License Number 6050			
Address	P.O. Box 347, Chase, KS 67524		
		: 14 Month: 4 Year:19 ⁹²	
Plugging (proposal received from Mike	e Kelso	
(company name) Kelso Casing Pulling, Inc. (phone) 316-938-2943			
were: 5½" at 4418' w/125 sx cement, Open hole from 4418-30'			
1st plug sand $5\frac{1}{2}$ " casing back to 4360' and dump 5 sx cement on top of sand through bailer,			
2nd plug pump 25 sx cement at 1500-1600' where parted,			
3rd plug pump 50 sx cement at 1000', 4th plug at 475' with 50 sx cement,			
5th plug	at 40' with 10 sx cement.		
Plugging Proposal Received by Case Morris			
Plugging Operations attended by Agent7: All X Part None			
Operations Completed: Hour: 11 a.m. Day: 16 Month: 4 Year: 1992			
ACTUAL PLI	• •	1 5½" casing back to 4360' and dumped 5 sx cement	
on top of sand through bailer, casing parted at 1500',			
2nd plug spotted 25 sx cement at 1500', 3rd plug layed down 5½" casing to 1000' and			
spotted 50	O sx cement, 4th plug layed dow	m 5½" casing to 500' and spotted 50 sx cement,	
5th plug layed down all 5½" casing and pumped into 8 5/8" surface casing with 300 lbs.			
hulls and	140 sx cement. Pumping pressu	ire 0-300 psi and shut in 100 psi. (Over) TON COMMUSE.	
Remarks:	Used 60/40 Pozmix 6% gel by Al	lied. Recovered 2000' of 5½" casing 17 2 4 1900	
	(If additional description	lied. Recovered 2000' of 5½" casing 17 2 4 1990 Is necessary, use BACK of this form 1/10/10/10/10/10/10/10/10/10/10/10/10/10	
· Ma Na	pobserve this plugging.		
TE	-5-9a	Signed Kkeand Cauben 4-24-1992	
A' NO' 37	V. NO. 33/47		
.,	وماه يها المومايليو ويستمين الما مراجيين الما والمعارفين أأيون أريبا الماء المياسا والمراد أأوا أراد المجاري وا	many many many manaka na anakamana arawahan na manaka na kata manaka na kata manya Rey • 0.1.=84,	

There was 500° more casing in the hole than estimated. Ran line on plug after spotting plug at 500°. Ran line to 540° and hit cement plug.