15-155-21322-00-00

Form C-5 (5/88)

STATE OF KANSAS - CORPORATION COMMISSION PRODUCTION TEST & GOR REPORT

TYPE TES		vision		PRODUCTIO			·		_	Form	C-5 Revise
The second secon	T: / Ini	tial /	Annual	Workove	r Recla	ssifice	tion	TEST	DATE:	3/26/93	
Company			•		PORTO		•			Wol	I No.
	con Exp	loration			Wilkins	on				. 1	
County		Lo	Location		Section		Township Range		Acres		
Reno		SW SW		9		23S 8W		8W	160		
Field				servoir			•	line Co	nnecti	on	٠.
Wile Completi	dcat			dississipp completion			NCRA			- Da - 1	ker Set At
•	0/93			Single	(Descritos)		3743		• D•		Kor Set At Die
Product1		od:	:	T	ype Fluid		ion	. λ	PI Grav	vity of	Liquid/01)
XXVVIXX	Pump	ing O	XXXXXXXX		Oil & Wate				35		
asing S	126	Weig			Set A		Porf	oration	_	To	
51			<u> 15.5</u>	5	37.			3	674 - 80		
		Woigh		I.D.	Set A		Porf	oration	5.	To	
2-7	/8		6.5	2	.5 368	35			665-36	70 /	<u> </u>
retest:										Du	ration Hr
tarting	Date		Timo		Ending	Date .		Tim	8		
ost:	, 	10=100		- 00	70-14		iac iaa				ration Hr
tarting	Date 3	/25/93		9:00am	Ending			Time	9:00	am 24	
				OIL PRODUC					عيدي		
		ad Press		•	Separat	or Pres	sure			Chok	e Size
asing:			ig: 15			, -					·
bls./In.				Starting Gauge			Inding Gauge			Net Prod. Bbls.	
	Size	Number	Feet	Inches	Barrels	Feet	Inche	a Bar	rels	Water	011
	· ·	•	1	ì	(:						
retest:	<u> </u>			<u> </u>	<u> </u>	<u> </u>	<u> </u>			ar .	1
est:	200	1	3	2	63.46	4	.11	98	3.53	25	10
<u> </u>							 				-}
est:	<u></u>	<u> </u>					<u> </u>				
	24.33	nnection		GAS PRODUC	TION OBSE	RVED DA	TA				
			_		•	ice Mat		_			:
ide Tabe	·	Flance	Taps:	,	Diff	erentis	l:	S	atic P	ressure	
easuring	Run-	Prover-	Or1: 1ce	Meter-Pro	ver-Teste	r Prossi	uro I	Mff. Pr	ess. C	ravity	Flowing
evice	Test	er Size	Size	In.Water	In Merc.	Psig or	(Pd) (hw) or	(hd) C	as (Gg)	Temp. (t)
rifice		ľ		1	,		- 1		1	1	
eter ritical				 -							
ricical low Prov	No.	gas in	excess (f what is	used to	run eng:	ine.				
rifice	91										
ell Test	.er			1 1	, L				[
				CAS FLOW R	ATTE CATCIII	ATTONG	791				
seff. MC	ភ្នំ ស្រ	leter-Pro		Extension	كأرمار ومنسوس	س و نوست کاری او		. Фот-	Desid		01
Fb)(Fp)(OWTC) Pres				Vhw x Pm		(Fg)	Sev+c=	Temp.			Chart
<u> </u>	/ .	(1 0	<u>-a/(124/</u>	y IIW X YE	F ACCO	- ACKATE	BUUDE	12.07	Factor	(vg 1)	Factor(Fo
					'	-		-	•	}	
- 				Oil Prod.		·	Gan /Ot	1 Ratio	·		Cubi C
	MCFD			~ •				OR) =	,		Cubic Ft
as Prod. low Rate	(R):	TSTM		Bbls./Dav	•		14.	. <i></i>			MAN DEI
as Prod. low Rate The und	(R): ersigna	d author	itv. on	Bbls./Day	the Compa	ny, sta	tes th	at ha i	a duly	Buthors	- od
as Prod. low Rate The und	(R): ersigna	d author	itv. on	behalf of	the Compa	ny, sta	tes th	at ha i	s duly	authori	per Bbl. zed
as Prod. low Rate The und o make t	(R): ersigne he abov	d author	ity, on and the	Bbls./Day behalf of at he has Executed	the Compa	of the	tes th	at he i stated	therei	n, and t	zed hat
as Prod. low Rate The und o make t	(R): ersigne he abov	d author	ity, on and the	behalf of	the Compa	of the	tes th	at ha i	therei	n, and t	- od
as Prod. low Rate The und o make t	(R): ersigne he abov rt is t	d author o report rue and	ity, on and the	behalf of	the Compa	of the	tes th	at he i stated	therei	n, and t	zed hat