

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION

APR 26 1974

CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Nadel & Gussman

Address 514 Union Center
Wichita, Kansas

Lease (Farm Name) Ulsh Well No. 1-A

Well Location NW NE SE Sec. 7 Twp. 25 Rge. 14 (E) (W) x

County Stafford Total Depth 4240' Field Name _____

Oil Well x Gas Well _____ Input Well _____ SWD Well _____ Rotary D & A _____

Well Log filed with application as required Yes

Date and hour plugging is desired to begin At once

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

Frank Neff Address Great Bend, Kansas

Plugging Contractor Southwest Casing Pulling Co. License No. 399

Address Box 364 Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to:

Name Nadel & Gussman

Address Box 14, Great Bend, Kansas 67530

and payment will be guaranteed by applicant or acting agent.

Southwest Casing Pulling Co
Signed: S. D. Miller
Applicant or Acting Agent

Date: April 25, 1974

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

April 26, 1974

WELL PLUGGING AUTHORITY

Well No.	1-A
Lease	Ulsh
Description	NW NE SE 7-25-14W
County	Stafford
Total Depth	4240'
Plugging Contractor	Southwest Casing Pulling


**Nadel & Gussman
514 Union Center
Wichita, Kansas 67202**

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. G. Russell Eiberstein, Attica, Kansas 67009
is hereby assigned to supervise the plugging of the above named well.