API NUMBER 15-047-20,700-00-00 STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202 TECHNICIAN'S PLUGGING REPORT Operator License 5 5056 Operator: F.G. Holl Name& 6427 Foot Vollogg API NUMBER 15-047-20,700-00-00 SW SW NW, SEC. 2 , T 25 s, R 17 w/gX 3080 feet from S section line Lease Name Hawley "C" Well 2-2 County Edwards 4565		¹ 060938	MAR 3 1987
SW SW NW SEC. 2	Tq: '	•	API NUMBER 15-047-20,700-00-00
Section line County Edwards County Edward	CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		
Departor License 5056 Lose Name Hawley "C" Mell 2-2			
Operator: F.G. Holl County Edwards /49.36 Named 6427 East Kellogg Well Total Depth 4565 feet Wichita, KS 67207 Conductor Pipe: Size feet Surface Casing: Size 8 5/8 feet 304 Abandoned Oll Well Sas Well X input Well SWD Well DAA Other well as hereinafter Indicated Plugging Contractor Kelse Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug et: Hour: 10:30 a.m. Day: 3 Month: 3 Year: 19 87 Plugging proposal received from Vernon Duntz (company name) Kelse Casing Pulling (phone) 316-938-2457 Were: 4½" at 4563' PETD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3 Sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, reléase 8 5/8" wiper plug and pump 130 sx cement. Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.m.bay: 3 Month: 3 Year: 19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement. 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pump 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (11 additional description is necessary, use BACK of this stops@shachDx commensure.			
NameA Address 6427 East Kellogg Well Total Depth 4565 feet Wichita, KS 67207 Conductor Pipe: Size feet feet Surface Casing: Size 8 5/8 feet 304 Surface Casing: Size 8 5/8 feet 304 Abandoned Oll Mell Gas Mell X input Well SWD Well D&A Other well as hereinafter Indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 vere: 4½" at 4563' PETD 4522' Perfs at 4427-31, 4417-21' lst plug CIBP at 4400' with 2 sx cement, 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, reléase 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.m.bay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement. 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6Z gel by Allied, Recovered 3400' of 4½" casing. (11 additional description is necessary, use BACK of this shopmethalancountession (11 additional description is necessary, use BACK of this shopmethalancountession)		•	Lease Name_Hawley C Well # 2-2
Mell Total Depth 4565 feet	Namal		
Surface Casing: Size 8 5/8 feet 304 Abandoned Oli Meii Gas Meii X 'nput Weii SWD Meii D&A Other Well as hereinafter Indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to ping at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 Were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' Ist plug CIBP at 4400' with 2 sx cement, 2nd plug 2nd pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.Day: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gal, 50 sx cement, 10 sx gal, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gal by Allied. Recovered 3400' of 4½" casing. (11 additional description is necessary, use 3ACK of this stormschusson)	Address	6427 East Kellogg	Well Total Depth 4565 feet
Abandoned Oli Weil Sas Weil X Input Weil SWD Weil DAA Other weil as hereinafter Indicated Plugging Contractor Kelso Casing Pulling ticense Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' Ist plug CTBP at 4400' with 2 sx cement, 3nd Plug 15, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 130 sx cement. Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a. Day: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CTBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (11 additional description is necessary, use BACK of this stogmesh)DARAIDN COMMASSION (11 additional description is necessary, use BACK of this stogmesh)DARAIDN COMMASSION		Wichita, KS 67207	Conductor Pipe: Sizefeet
Other well as hereinafter indicated Plugging Contractor Kelso Casing Pulling ticense Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' Ist plug CIBP at 4400' with 2 sx cement, 2nd plug 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.Day: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (11 additional description is necessary, use BACK of this stormeshousenesseness.)			Surface Casing: \$1ze 8 5/8 feet 304
Plugging Contractor Kelso Casing Pulling License Number 6050 Address Box 347, Chase, KS 67524 Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3 sx mulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement. 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (11 additional description is necessary, use 3ACK of this storgegiveration commuscion.	Abandoned	Oli Well Gas WellX	_ input Well SWD Well D&A
Address Box 347. Chase, KS 67524 Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CTBP at 4400' with 2 sx cement, 3 deceived by Paul Luthi (TECHNICIAN) Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.mbey: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CTBP at 4400' with 2 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pump 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormshoanion Commands and the stormshoanion commands and th	Other well	l as hereinafter indicated	
Company to plug at: Hour: 10:30 a.m. Day: 3 Month: 3 Year:19 87 Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 vere: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 2nd plug plug 1, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, reléase 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthí (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.m. Pay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormshowship Commendation Com	Plugging C	Contractor Kelso Casing Pulling	License Number 6050
Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3nd plug plug proposal plug and pump 130 sx cement. Plugging Proposal Received by Paul Luth1 (TECHNICIAN) Plugging Operations attended by Agent?: Ail X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 5% gel by Allied. Recovered 3400' of 4½" casing. (1f additional description is necessary, use BACK of this stagmand/DARAIDNICOMMANSGOON	Address	Box 347, Chase, KS 67524	
Plugging proposal received from Vernon Duntz (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3nd plug plug proposal plug and pump 130 sx cement. Plugging Proposal Received by Paul Luth1 (TECHNICIAN) Plugging Operations attended by Agent?: Ail X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 5% gel by Allied. Recovered 3400' of 4½" casing. (1f additional description is necessary, use BACK of this stagmand/DARAIDNICOMMANSGOON	Company to	plug at: Hour: 10:30 a.m. Day:	3 Month: 3 Year:19 87
(company name) Kelso Casing Pulling (phone) 316-938-2457 were: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3nd plug 1s, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, reléase 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stageney prantom communications)			
rere: 4½" at 4563' PBTD 4522' Perfs at 4427-31, 4417-21' 1st plug CIBP at 4400' with 2 sx cement, 3 sx nulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 130 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.may: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this storme-Dozanion communication.)	-	•	
Ist plug CTBP at 4400' with 2 sx cement, \$\frac{2\text{nd}}{3\text{ sx}}\text{Plug}\$ and pump 130 sx cement. Plugging Proposal Received by Paul Luth1 (TECHNICIAN) Plugging Operations attended by Agent7: All X Part None Operations Completed: Hour: 11:15 a. They: 3 Month: 3 Year: 19 87 ACTUAL PLUGGING REPORT 1st plug CTBP at 4400' with 2 sx cement. 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing.			
Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.may: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, I sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing.			
Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a. Day: 3 Month: 3 Year: 19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stopenes/Daradox Commission			
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (if additional description is necessary, use BACK of this storms: Delandon Commission	1 sx hull	s, release 8 5/8" wiper plug and	pump 130 sx cement.
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.mbay: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (if additional description is necessary, use BACK of this storms: Delandon Commission	<u>-</u>		
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.may: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, I sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (if additional description is necessary, use BACK of this stormer DORANDN COMMASSION			·
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 11:15 a.may: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormed) CRAMINSCION		Plugging Propo	·
Operations Completed: Hour: 11:15 a.may: 3 Month: 3 Year:19 87 ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (if additional description is necessary, use BACK of this storement) COMMMISSION	Plugotna A	Descriptions attended by Asserta. Al	
ACTUAL PLUGGING REPORT 1st plug CIBP at 4400' with 2 sx cement, 2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormer por all of the stormer por al			
2nd plug pump 3 sx hulls, 15 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5/8" wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this storemetroscon	•	 · <u>_</u>	
wiper plug and pumped 130 sx cement. Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormed DORAHON COMMISSION			
Maximum pressure 400 psi and shut in 150 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormed DORAHON COMMISSION			cement, 10 sx gel, 1 sx hulls, released 8 5/8"
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormes) ORATION COMMISSION	wiper plu	g and pumped 130 sx cement.	
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormes) ORATION COMMISSION			
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 3400' of 4½" casing. (If additional description is necessary, use BACK of this stormes) ORATION COMMISSION			
(If additional description is necessary, use BACK of this shorement DARATION COMMISSION	Maximum p	ressure 400 psi and shut in 150 p	si.
	Remarks:	Used 60/40 Pozmix 6% gel by Alli	ed. Recovered 3400' of 4½" casing.
illidity Washington (1) Lobserve this plugging.	NVA		necessary, use BACK of this shoremention commission
	i Naiki kha	ទៅទៅ ្រៀប់bserve this plugging.	D D DAR PRODU

FORM CP-2/3 Rev.01-84

Wichita, Kansas