

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. Box 17027
Wichita, Kansas 67217

FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

RECEIVED
STATE CORPORATION COMMISSION
SEP 24 1975
9124/75
CONSERVATION DIVISION
Wichita, Kansas

Lease Owner Icer Addis 15-057-20082-0000
Address P. O. Drawer 8038, Wichita, Kansas
Lease (Farm Name) Maxwell Well No. 1
Well Location C NE SE Sec. 22 Twp. 26S Rge. 24 (E) (W) XX
County Ford Field Name (If Any) _____
Total Depth 5200 Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ D & A X
Well Log filed with application Yes or Well Log filed with Plugging Supervisor _____

Date and hour plugging is desired to begin 6:00 A. M. September 9, 1975

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations R. L. Budig
Address Derby, Kansas

Plugging Contractor Union Drilling Co., Inc. License No. _____
Address 505 Union Center, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____
Icer Addis Address P. O. Drawer 8038, Wichita, Kansas

and payment will be guaranteed by applicant.

Signed: *R. L. Budig*
Applicant or Acting Agent

Date: September 12, 1975

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

September 11, 1975

5-057-20082-0000

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Maxwell
Description	C NE SE Sec. 22-26S-24W
County	Ford
Total Depth	5200'
Plugging Contractor	Union Drilling Co., Inc.


Icer Addis
Drawer 8038
Wichita, Kansas 67208

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Clarence Thomas, 403 Davis, Garden City, Kansas
is hereby assigned to supervise the plugging of the above
named well.