15-155-20109-0000 Form CP-4

	STATE	OF	KA	NSAS	
STATE	CORPOR	ATI	ON	COMMISSION	

WELL PLUGGING RECORD

ive All Information Completely lake Required Affidavit last or Deliver Report to:		WE		GGING R	ECOND	
Conservation Division State Corporation Commission ,		.		0	0.4	A
212 No. Market Wichita, Kansas		Reno	County	v. Sec. 2 1	wp. 24 W NE NE Rge	$\stackrel{\text{?}}{=}$ (E) $(V$
NORTH	Location as "N	E/CNW#SW#" o Scott	r footage from	m lines	M 116 116	
1030	Tease Owner	McEltr	• 775	 		11
	Lease Name Office Address_	77. 7	ta, Kansa	as		Well No
	Date well com	· -	•	• •		
<u> </u>						19
i	Plugging comm	plugging approve	30/69			19
	Plugging compl	leted	2/69			19
	Reason for abar	ndonment of well	or producing	formation	depleted.	
1		·				
	1					
Locate well correctly on above		yes	the Conserva	ation Division o	or its agents before	e plugging was co
Section Plat Name of Conservation Agent who super		711	an		·	
roducing formation			Bottom		Total Depth of W	/ell 3424 F
how depth and thickness of all water,			Dotton		TOTAL Depart of 11	· Ch
-	_					
OIL, CAS OR WATER RECORD	15 		<u>-</u> -		C.A	ASING RECORD
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT
			_	10-3/4	n 238	none
				5 <u>1</u> 1	3422	2808
				~ -		
					<u> </u>	
		<u> </u>				
					<u> </u>	
Describe in detail the manner in introducing it into the hole. If cemfeet for each plug seChecked bottom,Loaded hole, cut	ran sand to 3 t off poor boy	3300' and dr	e character of umped 5 ged up of	f same and dept sacks of c n $5\frac{1}{2}$, had	ement.	
checked bottom, Loaded hole, cut	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of c $5\frac{1}{2}$, had and pulle 35 sacks	ement. 11" d 90joints. of cement.	
Checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 20 Mudded to 40', 1	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of c $5\frac{1}{2}$, had and pulle 35 sacks	ement. 11" d 90joints. of cement.	
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of c $5\frac{1}{2}$, had and pulle 35 sacks	ement. 11" d 90joints. of cement.	
Checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 20 Mudded to 40', 1	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement.	
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent.	fee
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks of cem	ement. 11" d 90joints. of cement. ent.	fee
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent.	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent.	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe.	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	3300' and ding head, rig worked picked bridge and	umped 5 ged up o pe loose d dumped	sacks of con 5½", had and pulle 35 sacks cks of cem	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', T Tallied pipe. PLUGGING COMPLET	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock 10' rock bridg	are used, state the state that are used, right head, right worked pictoridge and dump	umped 5 ged up o pe loose d dumped ed 15 sa	sacks of company of the same and depth sacks of company of the sacks of company of the same and pulle so sacks of company of the same and pulle sacks of company of the same and pulle same and same a	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	SION
checked bottom, Loaded hole, cuttension. Shot p Bailed hole to 2 Mudded to 40', T Tallied pipe. PLUGGING COMPLET	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock	description is necessing PULLING	umped 5 ged up o pe loose d dumped ed 15 sa	sacks of company of the same and depth sacks of company of the sacks of company of the same and pulle so sacks of company of the same and pulle sacks of company of the same and pulle same and same a	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', T Tallied pipe. PLUGGING COMPLET	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg TE. (If additional KNICHT CAS)	description is necessing PULLING	umped 5 ged up o pe loose d dumped ed 15 sa	sacks of company of the same and depth sacks of company of the sacks of company of the same and pulle so sacks of company of the same and pulle sacks of company of the same and pulle same and same a	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS	Feet SION
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40', 1 Tallied pipe. PLUGGING COMPLET	ran sand to to off poor boy pipe at 2806', 235', 10' rock bridge to complete the control of the	ere used, state the 3300' and di y head, rig worked pi c bridge and ge and dump description is neces ING PULLING SAS	umped 5 ged up o pe loose d dumped ed 15 sa	sacks of con 5½", had and pulle 35 sacks of cem	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS L 1 1969 ATION DIVISION ita, Kansas	SION
checked bottom, Loaded hole, cuttension. Shot p Bailed hole to 2 Mudded to 40', T Tallied pipe. PLUGGING COMPLET	ran sand to to off poor boy pipe at 2806', 235', 10' rock bridge to complete the control of the	description is necessing PULLING	umped 5 ged up of pe loose d dumped ed 15 sa	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED ORATION COMMISS L 1 1969 ATION DIVISION ita, Kansas	SION
checked bottom, Loaded hole, cuttension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET	ran sand to to off poor boy pipe at 2806', 235', 10' rock bridge to rock bridge KNICHT CAST CHASE, KANSAS COUNCEL J. KNICHT	description is necessary of PULLING	umped 5 ged up of pe loose d dumped ed 15 sa eary, use BACK CO., IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED ORATION COMMISS 1 1 1969 ATION DIVISION ita, Kansas er or operator) of	SION The above-descri
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET Address TATE OF well, being first duly sworn on oath, s	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg KNIGHT CAST CHASE, KANS KANSAS NOEL J. KNIC	description is necessiNG PULLING A STATE OF (e) Cowledge of the formula is a second control of the first control	umped 5 ged up of pe loose d dumped ed 15 sa. Bary, use BACK CO.; IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED ORATION COMMISS 1 1 1969 ATION DIVISION ita, Kansas er or operator) of	SION The above-descri
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET Address TATE OF well, being first duly sworn on oath, s	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg KNIGHT CAST CHASE, KANS KANSAS NOEL J. KNIC	description is necessiNG PULLING A STATE OF (e) Cowledge of the formula is a second control of the first control	umped 5 ged up of pe loose d dumped ed 15 sa. Bary, use BACK CO.; IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED ORATION COMMISS 1 1 1969 ATION DIVISION ita, Kansas er or operator) of	SION The above-descri
checked bottom, Loaded hole, cuttension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg KNIGHT CAST CHASE, KANS KANSAS NOEL J. KNIC	description is necessiNG PULLING A STATE OF (e) Cowledge of the formula is a second control of the first control	umped 5 ged up of pe loose d dumped ed 15 sa. Bary, use BACK CO.; IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED ORATION COMMISS 1 1 1969 ATION DIVISION ita, Kansas er or operator) of	SION The above-descri
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET Address TATE OF well, being first duly sworn on oath, s	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg KNIGHT CAST CHASE, KANS KANSAS NOEL J. KNIC	description is necessing PULLING AND PULLIN	umped 5 ged up of pe loose d dumped ed 15 sa. Bary, use BACK CO.; IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. C5:V5D RATION COMMISS 1 1 1969 ATION DIVISION ita, Kansas er or operator) of its herein contained	SION The above-descri
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET Address TATE OF well, being first duly sworn on oath, s	ran sand to 3 t off poor boy pipe at 2806', 235', 10' rock lo' rock bridg KNIGHT CAST CHASE, KANS KANSAS NOEL J. KNIC	description is necessing PULLING AND PULLIN	umped 5 ged up of pe loose d dumped ed 15 sa. Bary, use BACK CO.; IN	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED DRATION CUMMISS L1 1969 ATION DIVISION ita, Kansas Address Address	SION N the above-described and the log of
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET Address TATE OF well, being first duly sworn on oath, s	ran sand to toff poor boy pipe at 2806', 235', 10' rock bridge to the same are true are true.	description is necessing PULLING SAS NTY OF RICHARD (Cooking of the find correct. So has a second content of the find correct. So has a second correct.	umped 5 ged up o pe loose d dumped ed 15 sa sary, use BACK CO., IN CE employee of co acts, stateme elp me God.	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED DRATION CUMMISS L1 1969 ATION DIVISION ita, Kansas Address Address	SION N the above-described and the log of
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET TATE OF well, being first duly sworn on oath, s bove-described well as filed and that	ran sand to toff poor boy pipe at 2806', 235', 10' rock bridge to the same are true are true.	description is necessing PULLING AND PULLIN	umped 5 ged up o pe loose d dumped ed 15 sa sary, use BACK CO., IN CE employee of co acts, stateme elp me God.	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED DRATION CUMMISS L1 1969 ATION DIVISION ita, Kansas Address Address	SION The above-described and the log of
checked bottom, Loaded hole, cut tension. Shot p Bailed hole to 2 Mudded to 40',] Tallied pipe. PLUGGING COMPLET PLUGGING COMPLET TATE OF well, being first duly sworn on oath, s bove-described well as filed and that	ran sand to toff poor boy pipe at 2806', 235', 10' rock bridge to the same are true are true.	description is necessing PULLING SAS NTY OF RICHARD (Cooking of the find correct. So has a second content of the find correct. So has a second correct.	umped 5 ged up o pe loose d dumped ed 15 sa sary, use BACK CO., IN CE employee of co acts, stateme elp me God.	sacks of complete sacks of com	ement. 11" d 90joints. of cement. ent. CEIVED DRATION COMMISS L 1 1969 ATION DIVISION ita, Kansas er or operator) of its herein contained tansas	SION The above-described and the log of

$\underline{R} \ \underline{O} \ \underline{T} \ \underline{A} \ \underline{R} \ \underline{Y} \quad \underline{D} \ \underline{R} \ \underline{I} \ \underline{L} \ \underline{L} \ \underline{E} \ \underline{R} \ \underline{S'} \quad \underline{L} \ \underline{O} \ \underline{G}$

OPERATOR:

A. Scott Ritchie

DRILLING COMMENCED: 4-13-69

412 Union Center

Wichita, Kansas

CONTRACTOR:

Graves Drilling Co., Inc.

DRILLING COMPLETED: 4-18-69

505 Union Center Wichita, Kansas

CASING RECORD:

238' of 10 3/4" casing, set LOCATION: McElwain #1 A

with 275 sacks cement; 5 1/2" casing, set at 3422'

SW/4 NE/4 NE/4 Sec. 2, 24S, 4W, Reno County

with 100 sacks cement

135 Sod and sand

I35 590 Shale

590 1965 Lime & shale

1965 2393 Lime

2393 2545 Lime & shale

2545 2665 Lime

2815 Lime & shale 2665

2815 2980 Lime

2980 3282 Lime & shale

3282 3424 Chert

3424 Total Depth

I hereby certify the foregoing statements to be true and correct, to the best of my knowledge.

GRAVES DRILLING CO., INC.

1.07/STATE OF KANSAS - SEDGWICK COUNTY

: 10 Subscribed and sworn to before me, a Notary Public, this 28th day of April, 1969.

My Commission Expires: July 28, 1970

Mary Ann Scott, Notary Public

RECEIVED STATE CORPORATION COMMISSION

JUN 25 1969

CONSERVATION DIVISION Wichila, Kansas