

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

Lease Owner The Atlantic Refg. Co. Address Box 17, Great Bend, Kansas
(Applicant)

Lease (Farm Name) Beitler Well No. 1

Well Location NE NW NE Sec. 27 Twp. 22 Rge. 8 (E)-(W)

County Reno Field Name (if any) Sterling

Total Depth 4015 Oil Gas Dry Hole X

Was well log filed with application? No. If not, explain:

Well log was attached to Well Plugging Record mailed to you Sept. 18, 1950

Date and hour plugging is desired to begin 8-29-50

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.

(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner

Stanton K. Myers Address Box 17, Great Bend, Kansas

Name of Plugging Contractor Lohman & Johnson

Address 320 Indiana Bank Bldg., Evansville, Indiana

Invoice covering assessment for plugging this well should be sent to

The Atlantic Refining Co. Address Box 17, Great Bend, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

SEP 26 1950 9-26-50

Stanton K. Myers
Applicant or Authorizing Agent

Date September 25, 1950

PLUGGING
FILE SEC 27 T 22 R 80
BOOK PAGE 25 LINE 10



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA 2, KANSAS

September 1, 1950

Well No.	1
Lease	Fetler
Description	NE NW NE 27-22-8W
County	Reno
File No.	25-10

Atlantic Refining Company
Box 17
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. C. D. Stough, Box 207, Great Bend, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR