Form CP-4

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely.
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 No. Market
Wichita, Kansas 67202

| NORTH | | | | | |
|-------|------------------|---------------|----------|--|--|
| | 1 | | | | |
| | | | <u> </u> | | |
| | | | ' | | |
| | ! ! | | | | |
| | ; ; | | | | |
| | ! ! | . | | | |
| | [[| | | | |
| 1 | [[| : | <u> </u> | | |

| Make Required Affidavit Mail or Deliver Report to: | , 1 . | VV.I | SLL PLO | GGING R | ECORD | | |
|---|-------------------------------------|---|----------------|-----------------|---------------------------------------|----------------------|---|
| Conservation Division State Corporation Commission | | | | | | | |
| 212 No. Market Wichita, Kansas 67202 | <u>S</u> | tafford | Count | y. Sec. 21 | Twp. 24 Rg | e <u>. 12</u> (E)_ | (W) × |
| NORTH | Location as "NE | CNWXSWX" (Gra | or footage fro | om lines | SE SE NE | | |
| | Lease Owner Lease Name | | ACO 17-17 | | | | |
| | Office Address_ | | ion Cent | er Wichit | a, Kansas | WELL INO | |
| | Character of W | | | | | - | |
| 1 1 1 | | | | _ | | | |
| 1 ! ! ! | Date well comp Application for p | plugging filed | - | 5- <u>28-71</u> | | | _19 |
| | Application for p | plugging approv | red | | | | _19 |
| | Plugging comme | enced | | 6-8-71 | · · · · · · · · · · · · · · · · · · · | | _19 |
| | | Application for plugging approved 19 Plugging commenced 6-8-71 19 Plugging completed 6-10-71 19 | | | | | |
| | Reason for aban | Reason for abandonment of well or producing formation | | | | | |
| | If a producing v | ll is abandon | | at an advettor | - | | 10 |
| | Was permission | | | | | | |
| Locate well correctly on above Section Plat | | | | | | Ziore piagging | |
| Name of Conservation Agent who supervi | ised plugging of this | s well | G. | R. Bibers | tein | | |
| Producing formation | D | epth to top | Bottor | n | . Total Depth o | of Well 410 | <u>)4 </u> |
| Show depth and thickness of all water, or | il and gas formation | s. | | | | | |
| OIL, CAS OR WATER RECORDS | | | | | | CASING RE | CORD |
| FORMATION | CONTENT | FROM | TO | SIZE | PUT IN | PULLED | OUT |
| FURMATIUN | CONTENT | FRUM | 10 | 5 1/2" | 4104 | | |
| | | | | 8 5/8" | 2701 | 3119.61 | |
| | | | | 0 3/0 | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | L | | <u> </u> | | <u> </u> | |
| Squeezed hole with 2 sack | s hulls, 15 s | sacks gel | and 100- | sacks come | nt. | | |
| | | | | <u> </u> | | | <u></u> |
| | | | - | | | | |
| | | | | | RECEI | VFD | |
| | | | | STA | TE CORPORATION | ON COMMISSIO | N |
| | | | | | JUN 1 | | 6-14-7 |
| | | | | | | | 4 |
| | - | | | Ç | ONSERVATION | Nancas DIAIDIAIDI | <u>. </u> |
| | | | | | Wichita. | Дапэаз | |
| | | _ | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| Name of Bluesias Commence | II additional) outhwest Casi | description is nece | Ssary, use BAC | | | | |
| | Box 364, Grea | | | | | | |
| Address | | 30 1701101 110 | WITO CARD | | | | |
| | | | | | | | |
| STATE OF Kansas | , COU | inty of <u>Ba</u> | cton | | , ss. | | |
| Southwest Casing Pull well, being first duly sworn on oath, say | | | | | | | |
| above-described well as filed and that the | | | | | | | -29 or ma |
| La Spirit | | (Signature) | , | , Some | (0.1) | d. | |
| \$ 2 U X | | | | grand | <u> </u> | <u> </u> | |
| 1 2 5 1 | • | | Box_36 | 14 Great | <u>Bend, Kans</u> (Address) | as | |
| Subscriped and Sworn to before | me this | day of_ | | | (ANGELESS) | 71 | i. |
| The Control of the Control | | uay or_ | <u> </u> | | Z ' ' V | - -! | |
| | · - r 10 | 17~ | <u>Undl</u> | my i | J. Wil | | 74.7.7 |
| My commission expires | - du 17 | | | U | | NOTATY | Public. |

FORMATION TOPS:

| • | Electric Log <u>Measurements</u> | |
|-----------------------|-------------------------------------|--|
| 8-5/8" Surface Casing | 270 | |
| Anhydrite | 702 (+1182) | |
| B/ Ambydaite | 722 (+1162) | |
| Heabner | 3323 (-1439) | |
| Toronto · | 3338 (-1454) | |
| Douglas Shale | 3358 (-1474) | |
| Brown Line | 3481 (-1597) | |
| Lansing-Ranses City | 3507 (-1623) | |
| B/ Kansas City | 3768 (-1884) | |
| Marmaton | 3 799 (- 1915) | |
| Kinderhook Shale | 3829 (-1945) | |
| Viola | 3912 (-2028) | |
| Simpson Shale | 4045 (-2161) | |
| Simpson Sand | 4062 (-2178) | |
| Arbuckle | 4101 (-2217) | |
| Total Depth | 4104 (-2220) | |

STRUCTURAL POSITION:

The structural position of this test can be compared with the following tests:

| | SHAWVER-ARMOUR #1 GRIEVE | STICKLE #1 BYER | REX & MORRIS |
|---------------------|-----------------------------|------------------------|------------------------|
| | NE NE SE 21-245-12N | SE SE NE 21-245-12W | SW SW NN 22-245-12W |
| Neebner | -3434 | -1439 | -1438 |
| Brown Lime | -1592 | -1597 | -1596 |
| Lansing-Kansas City | -1617 | -1623 | -1623 |
| Base Kansas City | -1879 | -1884 | -1884 |
| Kinderhook Shale | -1939 | -1945 | -1944 |
| Viola | -2020 | -2028 | -2023 |
| Simpson Shale | 400 | -2161 | LOS |
| Simpson Sand | · · | -2178 | • |
| Arbuckle | ** | -2217 | te- |
| Total Depth | -2022 | -2220 | -2074 |