

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner Strata Drilling, Inc. Address Box 355, Great Bend, Kansas  
(Applicant)

Lease (Farm Name) Davis Well No. 1

Well Location SW SE SW Sec. 3 Twp. 2 Rge. (E) 14 (W)

County Stafford Field Name (if any) \_\_\_\_\_

Total Depth 4240' Oil \_\_\_\_\_ Gas \_\_\_\_\_ Dry Hole X

Was well log filed with application? \_\_\_\_\_ If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin November 25, 1957

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

Jim B. McWilliams Address Box 355, Great Bend, Kansas

Plugging Contractor Strata Drilling, Inc.

Plugging Contractor's License No. \_\_\_\_\_

Address Box 355, Great Bend, Kansas

**RECEIVED**  
STATE CORPORATION COMMISSION  
12-16-57  
DEC 16 1957

Invoice covering assessment for plugging this well should be sent to Wichita, Kansas

Strata Drilling, Inc. Address Box 355, Great Bend, Kansas

and payment will be guaranteed by applicant.

Jim B. McWilliams  
Applicant or Acting Agent

Jim B. McWilliams

Date November 29, 1957

**PLUGGING**  
FILE SEC 3 T 24 R 14W  
BOOK PAGE 63 LINE 43

STATE OF KANSAS  
State Corporation Commission  
Conservation Division  
211 North Broadway  
Wichita, Kansas  
November 26, 1957


Well No.	1
Lease	Davis
Description	SW SE SW 3-24-24W
County	Stafford
File No.	63-13

Strata Drilling, Inc.  
Box 355  
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Don Truman, Rt. 1, Russell, Kansas Ph. 2046 (Gorham Kansas

Very truly yours,

  
Jewel M. Ogden  
Director of Conservation Division

cc:  
District Plugging Supervisor