STATE OF KANSAS

STATE CORPORATION COMMISSION

Give	All Information Complete.				
Make	Required Affidavit				
Mail	or Deliver Report to				
	Conservation Division				
	State Corporation Comm.				
	245 North Water				
	Wichita, KS 67202				

WELL PLUGGING RECORD

	~		7	4	ali ma a	i. The same workships
Make Required Affidavit	_Stafi		Com	ty. sec	24 IWP . Z	4 Rge 12W XEX/NX
Mail or Deliver Report to Conservation Division	Location as "NE/CNW4SW4" or footage from lines					
State Corporation Comm.	SW SE SW Lease Owner Rex & Morris Drilling Company					
245 North Water	Lease Name Brensing Well No. 1					
Wichita, KS 67202				ਹਨ। ਸੀ		
	Office Address P.O. Box 334, El Dorado, Kansas 67042 Character of Well (Completed as Oil, Gas or Dry Hole)					
				y Hole	5	
 	Date We	ell complet	ted		Augus	
1 1 1 1 1		tion for p				
		tion for p	-	approved		
		ng commence ng complete			Augus Augus	
		-		of well or		formation
	If a pr	oducing we	ell is a	bandoned,	date of 1	last production
Locate well correctly on above	Was per	mission of	otained	from the	Conservati	on Division or
Locate well correctly on above Section Plat	its age	ents before	e pluggi	ng was co	mmenced?	Yes
Name of Conservation Agent who su	pervised	plugging o	of this	well_Bil	1 Owens.	Sr
Producing formation	Dep	oth to top	Bo	ottom	Total Der	oth of Well39151
Show depth and thickness of all w	ater, oil	and gas	formatio	ns.	_	-
CTT OAG OR WAMED DECORDE						
OIL, GAS OR WATER RECORDS						ASING RECORD
STATE COTON TON CO	ONTENT	. FROM	то	SIZE	J'UT IN	, PULLED OUT
				8-5/8"	3241	None
AUG 25 1977						
COMSERVATION DIVISION						
COMSERVATION DIVISION Wichita, Ransus		 -	ļ		ļ	ļ
PHICHICAN		-	•	•	•	ı
Describe in detail the manner			_	-	_	
Describe in detail the manner was placed and the method or methology were used, state the character feet for each plug	oods used eter of sa	in introdume and dep	ucing it	into the	hold. It	f cement or other feet to
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotate.	oods used eter of sa set. ary mud	in introdume and dep	ucing it pth plac	into the ced, from rotary	hold. In	f cement or other feet to
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotation from the plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft.	oods used eter of sa set. ary mud t. and c	in introdume and dependent of the depend	ucing it pth places 5 ft. (with 40 300 ft	rotary 1	total der	f cement or other feet to oth) to Filled 800 ft. and
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotated by the plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft. The plug at 500 ft. Set plug	oods used cter of sa set. ary mud t. and c from 50 ent. Fi	from 391 emented 0 ft. to	ucing it pth place 5 ft. (with 40 300 fte with	rotary to sacks of the sacks of	total der	f cement or other feet to th) to Filled 300 ft. and
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotation from the plug at 500 ft. Set sol:	oods used eter of sa set. ary mud t. and c from 50 ent. Fi id plug	from 391 emented 0 ft. to 1led hol	5 ft. (with 40 300 ft e with and o	rotary to sacks of the sacks of	total der	f cement or other feet to th) to Filled 300 ft. and
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotated by the plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft. The plug at 500 ft. Set plug	oods used eter of sa set. ary mud t. and c from 50 ent. Fi id plug	from 391 emented 0 ft. to 1led hol	5 ft. (with 40 300 ft e with and o	rotary to sacks of the sacks of	total der	f cement or other feet to oth) to Filled 300 ft. and
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotater for each plug for the followith heavy rotater for each plug at 500 for hole with heavy rotary mud cemented with 35 sacks cemed 300 ft. to 40 ft. Set solution in the following sacks cement, 3 sacks cements for the following sacks cement, 3 sacks cements for the following sacks cements for th	ary mud t. and c from 50 ent. Fi id plug ment in	from 391 emented oft. to lled hol at 40 ft rat hole	yeing it pth place 5 ft. (with 40 300 fte with and continuous and continuous	rotary (rotary () sacks of the Set of the	total der cement. clug at 3 ctary muc to cella	f cement or other feet to th) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotation from the plug at 500 ft. Set sol:	ary mud t. and c from 50 ent. Fi id plug ment in	from 391 emented 0 ft. to 1led holat 40 ft rat hole	yeing it pth place 5 ft. (with 40 300 fte with and continuous and continuous	rotary (rotary () sacks of the Set of the	total der cement. clug at 3 ctary muc to cella	f cement or other feet to th) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotates 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cements 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cements accompany pump truck through 4=1/2 in pump truck through 4=1/2 in the sacks cements.	eter of sactor o	from 391 emented of ft. to lled hol at 40 ft rat hole tillizing l pipe.	to the place of th	rotary (rotary to sacks of the	total der cement. clug at a ctary muc to cella	f cement or other feet to oth) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations from the second plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set soll 12 sacks cement, 3 sacks cement plugging operations accompany pump truck through 4=1/2 in (If additional descriptions).	oods used eter of sa set. ary mud t. and c from 50 ent. Fi id plug ment in lished u nch dril	from 391 emented 0 ft. to 1led holat 40 ft rat hole tilizing 1 pipe. is necess	5 ft. (with 40 300 fte with and construction of the street	rotary (rotary for Sacks of Set y heavy rotemented)	total der cement. clug at a ctary muc to cella	f cement or other feet to oth) to Filled 300 ft. and d from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations for the set plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement. Plugging operations accompany pump truck through 4=1/2 in (If additional design) Name of Plugging Contractor Sun	eter of sactor o	from 391 emented 0 ft. to 1led hole at 40 ft rat hole tilizing 1 pipe. is necess 1 Cement	sucing it pth place 5 ft. (with 40 300 ft and construction of the sun of the	rotary (rotary to sacks of the Set y heavy rotary	total der cement. clug at a ctary muc to cella	f cement or other feet to oth) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations for the set plug at 500 ft. Set plug at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement. Plugging operations accompany pump truck through 4=1/2 in (If additional design) Name of Plugging Contractor Sun	eter of sactor o	from 391 emented 0 ft. to 1led holat 40 ft rat hole tilizing 1 pipe. is necess	sucing it pth place 5 ft. (with 40 300 ft and construction of the sun of the	rotary (rotary to sacks of the Set y heavy rotary	total der cement. clug at a ctary muc to cella	f cement or other feet to oth) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations from the plug at 500 ft. Set sol. 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement. 3 sacks cement plugging operations accompany pump truck through 4=1/2 in Set sol. Se	eter of sactor o	from 391 emented 0 ft. to 1led hole at 40 ft rat hole tilizing 1 pipe. is necess 1 Cement	sucing it pth place 5 ft. (with 40 300 ft and construction of the sun of the	rotary (rotary to sacks of the Set y heavy rotary	total der cement. clug at a ctary muc to cella	f cement or other feet to oth) to Filled 300 ft. and d from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotated for each plug. Filled hole with heavy rotary mud. Set plug at 500 for hole with heavy rotary mud. Cemented with 35 sacks cement. 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement. Plugging operations accompany pump truck through 4=1/2 in the sacks. (If additional descriptions accompany pump truck through 4=1/2 in the sacks.) STATE OF Kansas	ary mud t. and c from 50 ent. Fi id plug ment in lished u nch dril cription Oil Wel 169, Gr	from 391 emented 0 ft. to 1led hole at 40 ft rat hole tilizing 1 pipe. is necess 1 Cement	sucing it pth place 5 ft. (with 40 300 ft and construction of the sun of the	rotary (rotary to sacks of the Set y heavy rotary r	total dercement. clug at 3 ctary muc to cella	f cement or other feet to th) to Filled 300 ft. and from ar with
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotated for each plug. Filled hole with heavy rotary mud. Set plug at 500 for hole with heavy rotary mud. cemented with 35 sacks cement. 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement. Plugging operations accompany pump truck through 4=1/2 in the sacks. (If additional descriptions accompany beautiful descriptions. STATE OF Kansas Dean Britting, Agent	cods used eter of sate set. ary mud t. and c from 50 ent. Fi id plug ment in lished u nch dril cription Oil Wel 169, Gr	from 391 emented 0 ft. to 1led holat 40 ft rat hole tilizing 1 pipe. is necess 1 Cement eat Bend	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sun	rotary (rotary to sacks of the Set y rotary	total dercement. clug at 3 ctary muc to cella cementing this sheet	f cement or other feet to th) to Filled 300 ft. and from ar with ss.
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement plugging operations accompany pump truck through 4=1/2 in (If additional described well, being bean Britting, Agent of the above-described well, being	cods used eter of sacter o	from 391 emented of ft. to led hole at 40 ft rat hole tilizing l pipe. is necess cent Bend TY OF Security sworn	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum	t into the ced, from (rotary 1) Sacks of the Set y heavy rocemented L1 Well (BACK of the Set of	total dercement. olug at 3 otary muc to cella Cementing this sheet	f cement or other feet to th) to Filled 300 ft. and from ar with ss.
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotary mud comented with 35 sacks come 300 ft. to 40 ft. Set sol: 12 sacks cement, 3 sacks cement plugging operations accomp pump truck through 4=1/2 in (If additional described well, being the facts, statements, and matters)	cods used eter of sacter o	from 391 emented of ft. to led hole at 40 ft rat hole tilizing l pipe. is necess ceat Bend TY OF Security sworn contained	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum	rotary (rotary to sacks of heavy rotary rota	total dercement. olug at 3 otary muc to cella Cementing this sheet	f cement or other feet to th) to Filled 300 ft. and from ar with ss. TYPEXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement plugging operations accompany pump truck through 4=1/2 in (If additional described well, being bean Britting, Agent of the above-described well, being	cods used eter of sacter o	from 391 emented of ft. to led hole at 40 ft rat hole tilizing l pipe. is necess ceat Bend TY OF Security sworn contained	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum	rotary (rotary to sacks of heavy rocemented) BACK of the BACK of the sacks of the	total dercement. olug at 3 otary muc to cella Cementing this sheet	f cement or other feet to th) to Filled 300 ft. and from ar with ss. TYPEXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotary mud comented with 35 sacks come 300 ft. to 40 ft. Set sol: 12 sacks cement, 3 sacks cement plugging operations accomp pump truck through 4=1/2 in (If additional described well, being the facts, statements, and matters)	cods used eter of sate set. ary mud t. and c from 50 ent. Fi id plug ment in lished unch dril scription Oil Well 169, Gr COUNT g first description oue and conture and conture and conture and conture and conture the conture and conture the conture and conture the conture and conture the contu	from 391 emented of ft. to led hole at 40 ft rat hole tilizing l pipe. is necess ceat Bend TY OF Security sworn contained	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum	rotary (rotary to sacks of heavy rocemented) BACK of the BACK of the sacks of the	total dercement. olug at 3 otary muc to cella Cementing this sheet	f cement or other feet to th) to Filled 300 ft. and from ar with ss.
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotary mud comented with 35 sacks come 300 ft. to 40 ft. Set sol: 12 sacks cement, 3 sacks cement plugging operations accomp pump truck through 4=1/2 in (If additional described well, being the facts, statements, and matters)	cods used eter of sate set. ary mud t. and c from 50 ent. Fi id plug ment in lished unch dril scription Oil Well 169, Gr COUNT g first description oue and conture and conture and conture and conture and conture the conture and conture the conture and conture the conture and conture the contu	in introdume and designed and designed from 391 emented to ft. to led hold at 40 ft rat hole tilizing l pipe. is necessed Cement the feat Bend from Secondarined frect. So	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum of the property o	rotary (rotary to sacks of the sed, from the sacks of the	total dercement. clug at 3 clug at 3 cotary much to cella cementing this sheet her) ***X*** hat I have he above-de	f cement or other feet to th) to Filled 300 ft. and from ar with ss. FFEXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotary mud comented with 35 sacks come 300 ft. to 40 ft. Set sol: 12 sacks cement, 3 sacks cement plugging operations accomp pump truck through 4=1/2 in (If additional described well, being the facts, statements, and matters)	cods used eter of sate set. ary mud t. and c from 50 ent. Fi id plug ment in lished unch dril scription Oil Well 169, Gr COUNT g first description oue and conture and conture and conture and conture and conture the conture and conture the conture and conture the conture and conture the contu	in introdume and designed and designed from 391 emented to ft. to led hold at 40 ft rat hole tilizing l pipe. is necessed Cement the feat Bend from Secondarined frect. So	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum	rotary (rotary to sacks of heavy rotary to semented) BACK of the BACK of the God. I log of the God.	total dercement. clug at 3 clug at 3 cotary much to cella cementing this sheet her) ***X*** hat I have he above-de	f cement or other feet to th) to Filled 300 ft. and from ar with ss. TYPEXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotary mud comented with 35 sacks come 300 ft. to 40 ft. Set sol: 12 sacks cement, 3 sacks cement plugging operations accomp pump truck through 4=1/2 in (If additional described well, being the facts, statements, and matters)	cods used eter of sacter o	in introdume and designed and designed from 391 emented for the first hole at 40 ft rat hole fillizing lipipe. is necessal Cement eat Bend from Secontained frect. So mature)	sucing it pth place 5 ft. (with 40 300 ft e with and construction of the sum of the property on oath and the property on oath and the property on oath and the property of the	rotary (rotary to sacks of heavy rotary to semented) BACK of the BACK of the God. I log of the God.	total derement. clug at cotary much to cella Cementing this sheet her) exxect hat I have above decreased and the color of the colo	f cement or other feet to th) to Filled 300 ft. and from ar with ss. FFEXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Describe in detail the manner was placed and the method or method plugs were used, state the character feet for each plug. Filled hole with heavy rotations at 500 ft. Set plug at 500 ft. Set plug at 500 ft. hole with heavy rotary mud cemented with 35 sacks cement 300 ft. to 40 ft. Set sol. 12 sacks cement, 3 sacks cement 12 sacks cement, 3 sacks cement 14 sacks cement 15 sacks cement 16 sacks cement 17 sacks cement 17 sacks cement 18 sacks c	cods used eter of sacter o	in introdume and design and design and design and design and design at 40 ft. The state of the s	sun Of ary, use ing, Ir Kansa dgwick (RMRLS) on oath and the help me help me day Class	rotary (rotary for sacks of heavy rocemented ll Well (rotary for sacks of heavy rocemented ll Well (rotary for sacks of own, says: The God.)	total der cement. clug at 3 chary much to cella cementing this sheet char I have above de char Kandress) char I have above de char	f cement or other feet to th) to Filled 300 ft. and from ar with ss. ********************************

KANSAS GEOLOGICAL SOCIETY API NO. - 15-185-20,761 KANSAS WELL LOG BUREAU - KANSAS WELL SAMPLE BUREAU

KANSAS GEOLOGICAL SOCIETY BUILDING SOB EAST MURDOCK - WICHITA, KANSAS

COMPANY Rex & Morris Drilling Company

SED. 24 T. 245 R. 12W LOG SW SE SW

FARM Brensing

NO. 🤰

COUNTY Stafford

TOTAL DEPTH 39151 _{оомм.} August 8, 1977 SHOT OR TREATED

CONTRACTOR H-30, INC. ISSUED August 23, 1977 COMP. August 15, 1977

FIGURES INDICATE BOTTOM OF FORMATIONS

CASING

20 B-5/8" 324' cemented w/235 axs cement ELEVATION 1856 KB 15 12 13 PRODUCTION

Sand and Shale

3271

Red Bed and Shale

1,413

Shale and Red Bed

1,770

RECEIVED STATE CORPORATION COMMISSION

Shale and Lime Lime and Shale

3,915

1,950

AUG 25 1977

Rotary Total Depth

3,915

CONSERVATION DIVISION Wichita, Kansas

I hereby certify the above and foregoing to be a true and correct log of the above described well as shown by the drilling reports.

H-30, INC.

State of Kansas

County of Sedgwick

Subscribed and Sworn to before me a Notary Public in and for said county and state this 23rd. day of

August, 1977. VILLISO.

OTNRY.

Willison-Notary Public

My Commission Expires:

Wick Co 30, 1978