Rev. 6-3-74 FORM CP-1

## STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION 245 North Water WICHITA, KANSAS 67202

RECEIVED RECEIVED

WELL PLUGGING APPLICATION FORM

CONSERVATION DIVISION Wichita, Kansas File One Copy

Lease Owner C. A. Hoffman
Address 2840 South Eaton Way, Denver, Colorado 80227
Lease (Farm Name) Haselhorst Well No. 1
95 N of NE NE Well Location NW Sec. 6 Twp. 145 Rge. 15 (E) (W) X
County Russell Total Depth 3340' Field Name
Oil Well Gas Well Input Well SWD Well Rotary D & A D & A
Well Log attached with this application as required Yes
Date and hour plugging is desired to begin 6:00 P.M. 1-20-78
PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.  Name of company representative authorized to be in charge of plugging operations:
Stanley C. Lingreen Address Box 88, Russell, Kansas 67665
Stanley C. Lingreen Address Box 88, Russell, Kansas 67665  Plugging Contractor Revlin Drlg., Inc. License No.
Plugging Contractor Revlin Drlg., Inc. License No.
Plugging Contractor Revlin Drlg., Inc. License No.  Address P.O. Box 88, Russell, Kansas 67665
Plugging Contractor Revlin Drlg., Inc. License No.  Address P.O. Box 88, Russell, Kansas 67665  Invoice covering assessment for plugging this well should be sent to:

Date:

January 23, 1978



# State Corporation Commission

### CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

January 23, 1978

### WELL PLUGGING AUTHORITY

Well No.
Lease
Description
County
Total Depth
Plugging Contractor

Haselhorst 95' N NE NE NV Sec. 6-14-15W

Russell 3340

Revlin Drilling, Inc. & Allied Cementing Co.

C. A. Hoffman 2840 S. Eaton Way Denver, Colorado 80227

#### Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

Mr. <u>Duame I. Rankin. P.O. Box 967 Great Bond Konsas</u> 67530 is hereby assigned to supervise the plugging of the above named well.