

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

15-879-00647-0000

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Cherry Drilling Co., Address 102 Insurance Bldg.
(Applicant)
Lease (Farm Name) Hertzler Well No. 1
Well Location C S/2 N/2 NW Sec. 13 Twp. 23S Rge. 2 (W)-(W)
County Harvey Co. Field Name (if any) _____
Total Depth 3430 Oil Gas Dry Hole X
Was well log filed with application? YES. If not, explain: _____

Date and hour plugging is desired to begin 6:30 P. M. 4-27-57

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired. (Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____
R. C. Frost Address McPherson, Kansas
Name of Plugging Contractor Cherry Drilling Co., Inc.
Address 102 Insurance Bldg.


Invoice covering assessment for plugging this well should be sent to

Cherry Drilling Co., Inc. Address 102 Insurance Bldg. Wichita, Kansas

and payment will be guaranteed by applicant.

PLUGGING
FILE SEC. <u>13</u> T. <u>23</u> R. <u>2W</u>
BOOK PAGE <u>10</u> LINE <u>22</u>

5-4-1957


Applicant or Acting Agent

Date May 1, 1957



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS
May 2, 1957

15-079-00647-0000

Well No. 1
Lease Hertzler
Description CS/2 N/2 NW 13-23-2W
County Harvey
File No. 10-22


Cherry Drilling Co., Inc.
102 Insurance Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkee, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY



S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor