

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner Natural Gas & Oil Co. Address Box 105, Great Bend, Kansas  
(Applicant)

Lease (Farm Name) Kachelman Well No. 2

Well Location SW NE NW Sec. 36 Twp. 24 S Rge. (E) 14 (W)

County Stafford Field Name (if any) Koelsch, S.E.

Total Depth 4212 Oil X Gas    Dry Hole   

Was well log filed with application?    If not, explain:   

Well log attached.

Your representative will be  
Date and hour plugging is desired to begin notified prior to plugging

Plugging of the well will be done in accordance with the Rules and Regulations  
of the State Corporation Commission.

Name of the person on the lease in charge of well for owner   

K. W. Finney Address Box 105, Great Bend, Kansas

Plugging Contractor Not known at this time

Plugging Contractor's License No.   

Address   

Invoice covering assessment for plugging this well should be sent to   

Natural Gas and Oil Company Address Box 105, Great Bend, Kansas

and payment will be guaranteed by applicant.

9-14-1957

RECEIVED  
STATE CORPORATION COMMISSION

J. B. Steele  
Applicant or Acting Agent

Date September 13, 1957

PLUGGING

FILE SEC 36 T 24 R 14W CONSERVATION DIVISION  
BOOK PAGE 45 LINE 21 Wichita, Kansas

SEP 14 1957



STATE OF KANSAS  
 STATE CORPORATION COMMISSION  
 CONSERVATION DIVISION  
 211 NORTH BROADWAY  
 WICHITA, KANSAS  
 September 16, 1957


Well No.	2
Lease	Kachelman
Description	SW 1/4 NW 36-24-21W
County	Stafford
File No.	15-27

Natural Gas & Oil Company  
 Box 105  
 Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. H. Brundage, Box 283, Holsington, Kansas

Very truly yours,

  
 Jewel M. Ogden  
 Director of Conservation Division

cc:  
 District Plugging Supervisor