

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Natural Gas & Oil Company Address Route #1, Great Bend, Kansas
(Applicant)

Lease (Farm Name) Kachelman Well No. 4

Well Location NE SW NW Sec. 36 Twp. 24 Rge. (E) - (W) 14

County Stafford Field Name (if any) Koelsch, South East

Total Depth 4213' Oil Gas Dry Hole

Was well log filed with application? no If not, explain: Filed previously

Date and hour plugging is desired to begin Your representative will be notified prior
to plugging operation.
Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Mr. K. W. Finney Address Route #1, Great Bend, Kansas

Plugging Contractor Unknown

Plugging Contractor's License No. _____

Address _____

Invoice covering assessment for plugging this well should be sent to _____

Mr. K. W. Finney Address Route #1, Great Bend, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

APR 7 1955

CONSERVATION DIVISION
Wichita, Kansas

J. J. Davis

Applicant or Acting Agent

Date April 6, 1955

4-7-1955

CC: State Corporation Commission
File

PLUGGING
FILE SEC 36 T 24 R 14W
BOOK PAGE 109 LINE 40



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 800 BITTING BUILDING
 WICHITA 2, KANSAS
 April 7, 1955
 211 N. Broadway

Well No.	4
Lease	Kachelman
Description	NE SW NW Sec. 36-21-11N
County	Stafford
File No.	109-10

Natural Gas & Oil Company
 Route #1
 Great Bend, Kansas
 Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

BY: J. P. Roberts
 J. P. ROBERTS

cc: District Plugging Supervisor