STATE CORPORATION COMMISSION
CONSERVATION DIVISION - Plugging Section
130 S. Market, Room 2078
Wichita, Kansas 67202

	7.1. 1.101	IBER:15-095-		
	NM-NM-NM	SECTION_32_	TOWNSHIP_27	RANGE 5 W
OPERATOR LICENSE #_5086	4950	FEET FROM S	SECTION LINE	
OPERATORPintail Petro. Inc		FEET FROM E		
NAME <u>225 N. Market #300</u>	4950	רבנו רגטויו ב	SECTION LINE	
	7 H	Wilson Ondule	_ #1-1	
ADDRESS Wichita, KS. 67202		Wilson-Opdyk		
		Kingman		
	WELL IDIAL DEF	TH: <u>4650'</u> : <u>4 ½ @ 42</u> 8		15/./
	PIPE	: <u>4 ½ @ 428</u>		1011
· • V	SURFACE CASING	<u>8 5/8 @ 25</u>	9'	
ABANDONED OIL WELL GAS WELL	INPUT WELL	SWDX	D&A	
OTHER WELL AS HEREINAFTER INDICATED:	<u></u>			
PLUGGING CONTRACTOR: Quality Well Servi	ce			
ADDRESS: Sterling KS.				
COMPANY TO PLUG AT: HOUR: DAY:	MONTH:	YR:		
PLUGGING PROPOSAL RECEIVED FROM: Richard COMPANY NAME: Quality Well Service	<b>-</b>			
WERE: Open Hole- 4398-4650				
Sand back open hole to 4350 and				
Recover pipe.				
Spot 35 sks of cement at 850'				
Circulate cement from 350'-0'				
PLUGGING PROPOSAL RECEIVED BY:Butch Hoe	perecnt			•
PLUGGING OPERATIONS ATTENDED BY AGENT? ALL (				
ACTUAL PLUGGING REPORT: The open hole was of cement. The pipe was shot loose cement was spotted. The pipe was pusurface. The remaning pipe was pulpart at 2140'. Cement were deeper twas run to 180' and cement was again	e at 1890'and ulled to 350 led,and it was han expected	d pulled to 8 ' where cemen was discovered L Cement drop	50, where t was cir l that the ped to 18	35 sks of culated to pipe was
REMARKS: United cementing #'s 1564	<u> </u>	/40 4% gel		
KANSAS CORPORATION COMMISSION	0   C E   1/19/06	I DID MET OBSER	VE THIP'S PLUGG	ING.

CONSERVATION DIVISION WICHTA, KS

Q