

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Cities Service Oil Co. Address Box 751, Great Bend, Kansas
(Applicant)

Lease (Farm Name) Figger Well No. 1

Well Location 660' N. & 990' E. of W/4 Cor. Sec. 9 Twp. 24 Rge. 11W (E) - (W)

County Stafford Field Name (if any) Zenith

Total Depth 3781' Oil Gas Dry Hole

Was well log filed with application? Yes If not, explain: _____

Log attached.

Date and hour plugging is desired to begin As soon as possible.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

V. M. Conover Address Box 751, Great Bend, Kansas

Plugging Contractor Wilson, Inc. - Chas. D. Wilson, Oper.

Plugging Contractor's License No. _____

Address Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Cities Service Oil Company Address Box 751, Great Bend, Kansas

and payment will be guaranteed by applicant.

V. M. Conover
Applicant or Acting Agent

Date February 8, 1956.

RECEIVED
STATE CORPORATION COMMISSION
WICHITA, KANSAS

2-9-56
FEB 9 1956

CONSERVATION DIVISION
Wichita, Kansas

PLUGGING

FILE SEC 9 T 24 R 11W

BOOK PAGE 31 LINE 29



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

February 9, 1956

Well No.	1
Lease	Figger
Description	GE/2 SW 1W 9-24-11W
County	Stafford
File No.	37-29

Cities Service Oil Company
 Box 751
 Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. N. Grundge, Box 203, Hutchinson, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor