

15-095-01481-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Pickrell Drilling Company Address 705 Fourth Nat'l Bank Bldg.
(Applicant)
Lease (Farm Name) Casley "A" Well No. 1
well Location CN/2 NE NE Sec. 11 Twp. 28 Rge. 5 (E)-(W)
County Kingman Field Name (if any) _____
Total Depth 3826 Oil ___ Gas ___ Dry Hole x
Was well log filed with application? yes. If not, explain: _____


Date and hour plugging is desired to begin 11/27/54

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully and exceptions desired, None
(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____
Gerald W. Pike Address 705 Fourth Nat'l Bank Bldg.

Name of Plugging Contractor Pickrell Drilling Company
Address 705 Fourth National Bank Bldg., Wichita

Invoice covering assessment for plugging this well should be sent to _____
Pickrell Drilling Company Address 705 Fourth Nat'l Bank Bldg.
and payment will be guaranteed by applicant.


Applicant or Acting Agent

Date 11/29/54

PLUGGING
FILE SEC 11 T 28 R SW
BOOK PAGE 80 LINE 21

200 12.01.54



15 095 01481-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
~~300 BRITING BUILDING~~
WICHITA 2, KANSAS

November 29, 1954

211 N. Broadway

Well No.	1
Lease	Cadley "A"
Description	CW/2 NE NE 11-28-SW
County	Kingman
File No.	80-21

Pickrell Drilling Co.
705 4th Natl. Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: *J. P. Roberts*
J. P. ROBERTS

cc: District Plugging Supervisor