

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

15-155-62514-0000

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner S & S Pipe & Supply Co. Address P. O. Box 2513, Tulsa, Oklahoma  
(Applicant)

Lease (Farm Name) Sabin Well No. 5

Well Location CNW SE NE Sec. 13 Twp. 23 Rge. 4 (E) - (W)

County Reno Field Name (if any) \_\_\_\_\_

Total Depth 3641 Oil X Gas    Dry Hole   

Was well log filed with application? No If not, explain: \_\_\_\_\_

Will file with well plugging record

Date and hour plugging is desired to begin When pipe puller is available.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

Bert Self Address Hutchinson, Kansas

Plugging Contractor Bert Self

Plugging Contractor's License No. 48

Address Hutchinson, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

S & S Pipe & Supply Company Address Box 2513, Tulsa, Oklahoma

and payment will be guaranteed by applicant.

RECEIVED 9-3-1954  
STATE CORPORATION COMMISSION  
SEP - 3 1954  
Dan Schuster  
Applicant or Acting Agent  
Wichita, Kansas  
Date September 3, 1954

PLUGGING  
FILE SEC 13 T 23 R 4W  
BOOK PAGE 61 LINE 15



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
~~AGRICULTURE BUILDING~~  
WICHITA, KANSAS

September 3, 1954

211 N. Broadway

15-155-02514-0000

Well No.	5
Lease	Sabin
Description	CMW SE NE 13-23-1W
County	Reno
File No.	61-15

S & S Pipe & Supply Co.  
Box 2513  
Tulsa, Oklahoma

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkee, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

BY: J. P. Roberts  
J. P. ROBERTS

cc; District Plugging Supervisor