STATE OF KANSAS
STATE GORPORATION COMMISSION
Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
State Corporation Commission

WELL PLUGGING RECORD

0B

FORMATION PLUGGING RECORD Strike out upper line when reporting plugging off formations.

State Corporation Commission 801 Bitting Building Wichita, Kansas	, <u>.</u>					36""(%)""(%)""5"""(\
NORTH						
						Well No6
	Office Address	Petro	oleum Bld	g. Tulsa.	Okla.	weii No
	Character of Well (completed as	Oil, Gas or I	Dry Hole)	Oil	*** **************
- -	Date well completed	d			unknown	19
]						1946
	 Application for plug 	ging approve	ed	October	lst	1946
	Plugging commence	d	***************************************	October	.40000044040400400404040404040	1946
	Plugging completed			Occoper	drv -	1946
	Reason for adandon	ment of wen	or producing			***************************************
	If a producing well	is abandoned	l. date of last			19
						ore plugging was com-
Locate well correctly on above Section Plat ne of Conservation Agent who sup	menced?	****************		Mrs. Dos-	7 Primison	4
ne of Conservation Agent who sup	pervised plugging of this we	al		Mr. Rau	T Durkee	
lucing formation		top	Bottom		Total Depth of	Well 3397' Feet
w depth and thickness of all water	=					CASING PEGOED
L, GAS OR WATER RECORD						CASING RECORD
Formation	Content	From	То	Size	Put In	Pulled Out
***************************************				5 <u>-1</u> 11	33481	26001
· ·				7"-	3341!	1200'
			l I	13"	235!	none .
	ł I			•	Į.	
***************************************			, ,		1	
			i I			
cement-l	nt or other plugs were used g set. Dumped 2600 : Shot 7" of: bridge at 350!; tl	state the cl 	naracter of san 	me and depth it in bott coveredl	om of hole.	Shot pipeed hole and put
feet for each plug	nt or other plugs were used g set. Dumped 26001 Shot 74 of	state the cl 	naracter of san of cemen of and re ed surfac	me and depth it in bott coveredl	placed, from	Shot pipeed hole and put
feet for each plug	nt or other plugs were used g set. Dumped 26001. Shot 7" of bridge at 3501; t	state the cl 8—sacks f at 250 hen mudd	of cemen	me and depth it in bott covered l	placed, from	Shot pipe d hole and put t plug at top
feet for each plug	nt or other plugs were used g set. Dumped 26001. Shot 7" of bridge at 3501; t	state the cl 8—sacks f at 250 hen mudd	of cemen	me and depth it in bott ecovered l	placed, from	Shot pipe d hole and put t plug at top
off at cement l	nt or other plugs were used g set. Dumped 2600! Shot 7" of bridge at 350!; t	8 sacks f at 250 hen mudd	of cemen	me and depth it in bott ecovered l	placed, from	Shot pipe d hole and put t plug at top
off at coment l	Dumped 26001. Shot 74 of bridge at 3501; t	state the cl 8 sacks f at 250 hen mudd	of cemen	me and depth it in bott ecovered l	placed, from	Shot pipe d hole and put t plug at top
off at coment l	Dumped 26001. Shot 74 of bridge at 3501; t	state the cl 8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott covered le pipe an	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment l	nt or other plugs were used g set. Dumped 2600! Shot 7" of bridge at 350!; t	state the cl 8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott ecovered l	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment learning surface.	Dumped 26001. Shot 7" of bridge at 3501; t	8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott covered le pipe an	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment learning surface.	Dumped 26001. Shot 74 of bridge at 3501; t	8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott covered le pipe an	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment learning surface.	Dumped 26001. Shot 7" of bridge at 3501; t	8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott covered le pipe an	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment learning surface.	Dumped 26001. Shot 7" of bridge at 3501; t	8 sacks f at 250 hen mudd	of cemer Of and re	me and depth it in bott covered le pipe an	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment learning surface.	Dumped 26001. Shot 74 of bridge at 3501; t	state the classic state the cl	of cemen	me and depth	placed, from om of hole. 200!. Mudde ad put cemen	Shot pipe d hole and put t plug at top
off at coment to surface.	Dumped 26001. Shot 7" of bridge at 3501; t	state the classics of at 250 hen mudd	of-cemen 01 and re ed surfac	me and depth it in bott covered l e pipe ar	placed, from	Shot pipe ed hole and put t plug at top
off at cement surface.	Dumped 26001. Shot 7" of bridge at 3501; t	state the classics of at 250 hen mudd	of cemen 01 and re ed surfac	me and depth it in bott covered l ce pipe an	placed, from om of hole. 200!. Mudde d put cemen	Shot pipe d hole and put t plug at top
off at coment is surface.	Dumped 26001. Shot 7" of bridge at 3501; t	state the classics of at 250 hen mudd	of cemen 01 and re ed surfac	me and depth it in bott covered l ce pipe an	placed, from om of hole. 200!. Mudde d put cemen	Shot pipe d hole and put t plug at top
off at cement surface. Correspondence regarding this we ress.	Dumped 26001. Shot 7" of bridge at 3501; to the short of the short of the short of the short of the should be addressed to the sh	state the classic state the cl	of cemen 01 and re ed surface Kaiser 1sa,Okla	me and depth it in bott covered l ce pipe an	placed, from	Shot pipe d hole and put t plug at top
off at coment leading this weress.	Dumped 26001. Shot 7" of: bridge at 3501; to (If additional descripted should be addressed to	state the classics of at 250 hen mudd line is necessary Herman Bldg., Tu	of cemen 01 and re ed surface Kaiser Lsa,Okla,	me and depth it in bott covered l ce pipe an	placed, from	Shot pipe ed hole and put it plug at top
Correspondence regarding this we ress TE OF Oklahoma Berthold Neuwa	Dumped 26001. Shot 71 of bridge at 3501; t OK PAGE 20.006. (If additional descript ell should be addressed to	state the classic state the cl	of cemen Of and re ed surface , use BACK of 1 Kaisar Lsa,Okla.	t in bott covered l e pipe ar ipe & Sur	placed, from	Shot pipe d hole and put t plug at top -23-4/6
Correspondence regarding this we ress TE OF Oklahoma Berthold Neuwa	Dumped 26001. Shot 71 of bridge at 3501; t OK PAGE 20.006. (If additional descript ell should be addressed to	state the classic state the cl	of cemen Of and re ed surface , use BACK of 1 Kaisar Lsa,Okla.	t in bott covered l e pipe ar ipe & Sur	placed, from	Shot pipe ed hole and put at plug at top
Correspondence regarding this we ress TE OF Oklahoma Berthold Neuwa	Dumped 26001. Shot 71 of bridge at 3501; to OK PAGE 201116. (If additional descripted should be addressed to	state the classics, state the facts, state the classics and state the classi	of cemen Of and re ed surface , use BACK of 1 Kaisar Lsa,Okla.	t in bott covered l e pipe ar ipe & Sur	placed, from	Shot pipe ed hole and put at plug at top
Correspondence regarding this we ress.	Dumped 26001. Shot 71 of bridge at 3501; to OK PAGE 201116. (If additional descripted should be addressed to	state the classics, state the facts, state the classics and state the classics	of cemen 01 and re ed surface with the surface the surface disa, Okla.	t in bott ecovered l e pipe ar ipe & Sur er) we want	placed, from	Shot pipe ed hole and put top of the log of the above-
Correspondence regarding this we ress. TE OF Oklahoma Berthold Neuwa	Dumped 26001. Shot 71 of bridge at 3501; to OK PAGE 201116. (If additional descripted should be addressed to	state the classics, state the facts, state the classics and state the classics	of cemen 01 and re ed surface with the surface the surface disa, Okla.	t in bott ecovered l e pipe ar ipe & Sur er) we want	placed, from	Shot pipe ed hole and put top ed hole and put top ed top e
Correspondence regarding this we ress. TE OF Oklahoma Berthold Neuwa g first duly sworn on oath, says:	Dumped 26001. Shot 71 of bridge at 3501; t OK PAGE 20.006 (If additional descript ell should be addressed to	state the classic state state the classic state	of cemen of and reed surface of s	t in bott ecovered l e pipe ar ipe & Sur er) we want	placed, from	shot pipe and put top at top a
Correspondence regarding this we ress TE OF Oklahoma Berthold Neuwa	Dumped 26001. Shot 71 of bridge at 3501; t OK PAGE 20.006 (If additional descript ell should be addressed to	state the classic state state the classic state	of cemen of and reed surface of s	this sheet) ipe & Sur ace Bldg.	placed, from	shot pipe ed hole and put t plug at top ed hole and put top ed hole above-described well, the log of the above-
Correspondence regarding this we ress. TE OF Oklahoma Berthold Neuwa first duly sworn on oath, says: ibed well as filed and that the say	Dumped 26001. Shot 7" of bridge at 3501; the bridge at 3501; the bridge at 3501. The b	state the classic state state the classic state	of cemen of and reed surface of s	t in bott ecovered l e pipe ar ipe & Sur er) we want	placed, from	shot pipe and put top at top a

10-1-36 COMMENCED 11-3-36 COMPLETED ELEVATION 1470:

CASING RECORD

1311 40# 2431 711 24# 33121 5 3/16" 20# 33201 7" Cem. W/250 Sac. 5 3/16" " 30 Sac.

OLSON XXX COMPANY NE SW SE 34 23S 4W RENO COUNTY, KANSAS. E.J. England # 6

0 112--Sand

164--Shells & gravel

243--Sand & shells

417--Shale

612-Broken lime & shale

42-- "

59--Lime, hard

735--Broken lime

860--Shale & shells

960-- ** Lime

1030--Broken lime

40--Shale & shells

, hard 1110-- 11

56--Lime, hard

1640--Shale & shells

1725-- "

_1845-- ** tf

2060-- " lime

96--Lime

2152--Shale & lime

86--Lime

2223-- " , hard 2368-- " & shale

82--Broken lime

2415--Lime

41--Broken lime

73--Lime

2518-Sandy Shale

32--Lime

55--Shale

68--Broken lime

2934--Time

47--Shale & lime

55-- "

3102--Lime

3215--Shale & lime sh.

53-- . " , War.

3333--chat, R.u.s.t.

3344--Lime

3375 -- chat

T.D.

FILE 34 23 44)
EOOK FAGL 70 HE 40

٤,,

