

CARD MUST BE SIGNED

☐ **East**

..... SW SE Sec 9 Twp 24 S, Rge 22 ☒ West
(location)

.....554'..... **Ft North from Southeast Corner of Section**

...2086'..... **Ft West from Southeast Corner of Section**

(Note: Locate well on Section Plat on reverse side)

Nearest lease or unit boundary line554..... feet.

CountyHodgeman.....

Lease NameHerrmann..... Well# 15-9.....

Domestic well within 330 feet : ☐ yes ☒ no

Municipal well within one mile : ☐ yes ☒ no

☒ Oil ☐ Swd ☐ Infield ☒ Mud Rotary

☒ Oil ☐ Swd

☐ Gas ☐ Inj ☒ Pool Ext.☐ **OWWO** ☐ **Expt** ☐ **Wildcat** ☐ **Cable**

If OWWO: old well info as follows:

Operator

Well Name

Comp Date Old Total Depth

Projected Total Depth 4700 feet

Projected Formation at TD..Mississippi.....

Expected Producing Formations Mississippi

I certify that we will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to N.C.C. specifications.

Date Aug. 15, 1985 Signature of Operator or Agent _____

Depth to Bottom of fresh water 240 feet

Lowest usable water formation Dakota.....

Depth to Bottom of usable water400..... feet

Surface pipe by Alternate : 1 ☒ 2 ☐

Surface pipe to be set 400 feet

Conductor pipe if any required -0- feet

Ground surface elevation 2336' feet **MSL**

This Authorization Expires 2-20-86


Approved By RC# 8-20-85

Owner

Must be filed with the K.C.C. five (5) days prior to commencing well
This card void if drilling not started within six (6) months of date received by K.C.C.

Important procedures to follow :

A Regular Section of Land
1 Mile = 5,280 Ft.



1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to plugging, prepare a plugging plan, then obtain agreement from the appropriate district office for an approved plugging plan.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.
9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

AUG 20 1985

State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202
(316) 263-3238