TO:

STATE CORPORATION COMMISSION **CONSERVATION DIVISION - PLUGGING** 

266 N. Main St., Ste. 220 Wichita, KS 67202-1513

API Well Number: 15-015-19251-00-00

Spot: SWSENE

Sec/Twnshp/Rge: 13-26S-4E

2937 feet from S Section Line,

904 feet from E Section Line

Lease Name: TAGUE

Well #: 2

County: BUTLER

Total Vertical Depth: 2497 feet

Operator License No.: 5610

Op Name: BRUCE OIL COMPANY, L.L.C.

Address: 1704 LIMESTONE RD MCPHERSON, KS 67460

	String PROD			Depth (ft) 2492	Pulled (ft)	Comments 0 SX	
,	SURF	8.625	1	85		0 SX	

Well Type: OIL

**UIC Docket No:** 

Date/Time to Plug: 04/04/2016 12:00 AM

Plug Co. License No.: 30280

Plug Co. Name: SUNFLOWER WELL SERVICE, INC.

Proposal Rcvd. from: LEVI KOEHN

Company: BRUCE OIL CO

Phone: (620) 241-2938

Proposed AS PER KCC RULES & REGS Plugging

Method:

Plugging Proposal Received By: JONATHAN HILL

WitnessType: PARTIAL

Date/Time Plugging Completed: 04/07/2016 2:00 AM

KCC Agent: JONATHAN HILL

## **Actual Plugging Report:**

ABD. ARBUCKLE WELL FROM CIRGA: 1951; UNKNOWN WHEN LAST PRODUCED. WELL WAS NOT SHUT IN. 4/5/2016 (KCC WITNESSED). 1) RIGGED UP OVER HOLE, RAN IN W/TBG AND HIT BRIDGE AT 150', PULLED OUT OF HOLE AND PUT DRILL COLLAR ON. 2) RAN IN HOLE W/BIT, WASHED DOWN TO APPROX. 550' AND HIT UNKNOWN, SOLID BRIDGE: DRILLED THROUGH BRIDGE, DOWN TO 612', 3) FROM 612' APPROX. 750', HARD DRILLING. CIRCUALTING SCALING AND GRAY FLAKES. APPEARS TO BE CIRCULATING DRILL MUD, TUBING STRING POSSIBLY OUTSIDE OF CASING. 4) PULLED OUT OF HOLE - PULLED 25K GETTING CLEAR. LAST 3 TUBING JOINTS HAVE SIGN OF DRILL MUD ON OUTSIDE - DETERMINED LIKELY OUTSIDE OF CASING APPROX 612'. 4/6/2016 (KCC NOT WITNESSED, BUT UPDATED ON WORK BEING PERFORMED) 1) RAN IN HOLE W/SMALL IMPRESSION BLOCK, DID NOT MAKE IT PAST OBSTRUCTION AT APPROX. 610'. MOLD NOT CLEAR WHAT OBSTRUCTION WAS. 2) RAN IN HOLE W/ TAPERED MILL TO 600', MILLED FOR 4 HOURS - NO DEPTH MADE, NO CHANGE IN RETURNS, HOLE REMAINING FULL. 3) PULLED OUT OF HOLE, ATTEMPTED TO RUN 1" ON BACKSIDE OF 5.5" CASING, APPROX. 10' DOWN SOLID ALL AROUND, DETERMINED TO BE CEMENT. DUE TO CEMENT ON BACKSIDE AND DETERIORATING HOLE CONDITONS, DECISION MADE TO PLUG W/O BOTTOM PLUG INSTALLED. 4) RAN TUBING BACK IN TO APPROX, 600' AND PUMPED 73 SXS CLASS A CEMENT WITH W/2% CACL, CIRCUALTED CEMENT TO SURFACE. 4/7/2016 (KCC WITNESSED). VERIFIED CEMENT AT SURFACE INSIDE 5.5" CASING. CASING TO BE CUT DOWN AND BURIED AND PIT FILLED IN.

## Perfs:

Top Bot Thru Comments 2492 2497 OH

Remarks: CEMENTING COMPLETED BY CONSOLIDATED OIL WELL SERVICES, EL DORADO, KS. TICKET #: 51703. aremarke of disease have been arreaded to the sections

non kalelenen i i ietoko ako

Plugged through: TBG has built by a state of the best year between Charles and the HOCE years be

SION REPLETI

District: 02

Received KANSAS CORPORATION COMMISSION

JUN 2 3 2016

(TECHNICIAN)

1111 -7 2016