

15-169-00105-0000

KCC OIL/GAS REGULATORY OFFICES

Date: 06/16/16

District: 02

Case #: _____

New Situation

Lease Inspection

Response to Request

Complaint

Follow-Up

Field Report

Operator License No: 31934

API Well Number: 15-169-00105 0000

Op Name: Casebeer Inc.

Spot: NW NW NW Sec 32 Twp 16 S Rng 3 E W

Address 1: 909 High drive

330 Feet from N S Line of Section

Address 2: _____

330 Feet from E W Line of Section

City: McPherson

GPS: Lat: 38.62276 Long: 97.68433 Date: _____

State: Kansas Zip Code: 67460 -2908

Lease Name: Holm Well #: 1

Operator Phone #: (620) 504-5126

County: Saline

Reason for Investigation:

Verify Well has been plugged

Problem:

Well has been plugged. There are no records of the well being plugged

Persons Contacted:

Mark Casebeer

Findings:

Well was excavated and shown to have cement to the top.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

The well has been verified to have been cemented to the surface and should be listed as plugged.

Verification Sources:

Photos Taken: yes

<input checked="" type="checkbox"/> RBDMS	<input checked="" type="checkbox"/> KGS	<input type="checkbox"/> TA Program
<input type="checkbox"/> T-I Database	<input type="checkbox"/> District Files	<input type="checkbox"/> Courthouse
<input checked="" type="checkbox"/> Other: <u>Mark Casebeer / Casebeer Inc.</u>		

By: Jerry Sparling

Environmental Compliance Regulatory Specialist

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: _____

JK



6-16-16
FALCON FORESTRY CORPORATION
Hole #1, 15-169-00105
Site 327W 165-Rug 3W SALIDE