

# STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION P. O. BOX 17027 Wichita, Kansas 67217

Rev. 3-15-72 FORM CP-1

STATE CORPORATION COMMISSION

APR 22 1974

CONSERVATION DIVISION

Wichita, Kansas

## WELL PLUGGING APPLICATION FORM File One Copy

Lease Owner Robin Supply Company Address 1322 East 50th, Tulsa, Oklahoma Lease (Farm Name) Hoffman #8 Well No. Well Location SI, C N/2 N/2 SW/4 Sec. 19 Twp. 16S Rge. 11W (E) (W) County Barton Total Depth 3347' Field Name Oil Well Gas Well Input Well SWD Well Rotary D & A Well Log filed with application as required Date and hour plugging is desired to begin immediately PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION. Name of company representative authorized to be in charge of plugging operations: Lloyd Fletcher Address Claflin, Kansas Plugging Contractor Kelso Casing Pulling License No. 683Address Box 176, Chase, Kansas 67524 Invoice covering assessment for plugging this well should be sent to: Robin Supply Co. Address\_\_\_\_\_ 1322 East 50th, Tulsa, Oklahoma and payment will be guaranteed by applicant or acting agent.

> Signed: Rossell Keles by Margaret Incheser Applicant or Acting Agent

Date: April 19, 1974



## State Corporation Commission

#### CONSERVATION DIVISION

(Oil, Gas and Water) P.O. Box 17027 3830 S. Meridian WICHITA, KANSAS 67217

April 22, 197\$TATE CORPORATION COMMISSION

JUN 24 19/4

CONSERVATION DIVISION Wichita, Kansas

### WELL PLUGGING AUTHORITY

Well No.

8

Lease

Hoffman

Description

C N/2 N/2 SW 19-16-11W

County

Barton

Total Depth

3347\*

Plugging Contractor Kelso Casing Pulling

Robin Supply Company 1322 East 50th Street Tulsa, Oklahoma 74105

#### Gentlemen:

۲.

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

Donald Truan, P. O. Box 148, Russell, Kansas 67665 is hereby assigned to supervise the plugging of the above named well.