KANSAS STATE CORPORATION COMMISSION

WELL PLUGGING SUPERVISOR'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market

* a 4 a 4 a 4



√ichita 2, Kansas			,	
File No	Location:	NW NW SE		·7
	Sec			
	•			
I have this date comp	leted supervision of pl	lugging of:		
Vell No. # 1	LeasePolcy	n		
	R. P. Nixon			
	754 E. Wichita, R			
	Triangle Drilling			
	Great Bend, Kansa			
	Gas WellInput			
	rilled dry hole did ope			
	F			
peration Completed:	Hour 8:00P.M.Day 30			
he above well was plu				
_	with heavy mud to 2	200 ! set nl:	ue A ear hui	11a & 25
	irill pipe. Mud to			
	ented to the base of		-	. I , 5022
Cemeiro wirier ceme	Mided to the base of	1 0110 001141	•	
				
				
	·			
		A		
	the above well was plu we well was being plugg		stated and the	t I was
	Sign	ed: Dow Well	Trunk	/ .
	•	Well	Plugging Super	visor
	was not present while vledge and belief it wa			
or my not being prese	ent is as follows:	- 1		6-4-
		·	د تورد می ایران د توسط اماد میداد	- A A A A A A A A A A A A A A A A A A A
				.,,,,
		·····		4 1958
0/	R Sign	ed:		TON DIVISION a. Kansas
eviewed: J. Lewe. Field Supe	rvisor DILIC	GGING Well	Plugging Supe	rvisor
emarks://		9 T 13 R 15W		

BOOK PAGE 104 LINE 35