

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
800 BITTING BUILDING  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner SHELL OIL COMPANY Address P. O. BOX 426, WICHITA 1, KANSAS  
(Applicant)

Lease (Farm Name) L. ABBOTT Well No. 3

Well Location NW SW NE Sec. 25 Twp. 24 Rge. (E)-(W) 14

County STAFFORD Field Name (if any) KOELSCH, S.E.

Total Depth 4211 Oil  Gas  Dry Hole

Was well log filed with application? YES If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin MAY 10, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

H. E. NACHTIGAL Address P. O. BOX 341, CHASE, KANSAS

Plugging Contractor FORBES CASING PULLING COMPANY

Plugging Contractor's License No. 49

Address GREAT BEND, KANSAS

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

SHELL OIL COMPANY Address P. O. BOX 744, GREAT BEND, KANSAS

and payment will be guaranteed by applicant.

*R E Clark*

Applicant or Acting Agent

RECEIVED  
STATE CORPORATION COMMISSION  
MAY 21 1956

Date MAY 8, 1956

1b

CONSERVATION DIVISION  
WICHITA, KANSAS

5-9-56

PLUGGING  
FILE SEC 25 T 24 R 14W  
BOOK PAGE 60 LINE 9



15-195-12989-0000

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

May 9, 1956

Well No. 3  
Lease Abbott  
Description NW SW NE 25-24-24W  
County Stafford  
File No. 60-9

Shell Oil Company  
P. O. Box 764  
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Brundage, Box 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By S. S. Greider  
S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor