

KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION AGENT'S REPORT

TO:  
Jewel M. Ogden, Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: STAFFORD

Location: NW-SW-SE Sec. 32 Twp. 24 Rge. 14 (E) (W)

Name of Field: \_\_\_\_\_ Total Depth: 215'

I have this date completed supervision of plugging of:

Lease Name: GLASSCOCK "B" Well No. 1

Operator's Full Name: PETROLEUM INC

Complete Address: RR # 2 GT BEND, KANS

Plugging Contractor: CO TOOLS

Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A \_\_\_\_\_

Other well as hereafter indicated: LOST HOLE

Was any delay in plugging operations caused by Conservation Division Agent? Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 11<sup>00</sup> PM Day 31 Month MAY Year 1960

The above well was plugged as follows:

8 7/8" - 215'

LOST BOTTOM 2 JOINTS SURFACE PIPE -

SPOTTED 20 SW CRT @ 200' - MUDDED TO

35' - SET PLUG - CAPPED TO BASE OF COLLAR -

SKIDDED RIG 10' - EAST - STARTED NEW HOLE.

RECEIVED  
STATE CORPORATION COMMISSION

JUN 7 1960

CONSERVATION DIVISION  
Kansas

Signed: Frank Brunsford  
Conservation Division Agent

Reviewed: J. Lewis Brock  
Field Supervisor

Remarks:

INVOICED

DATE 9-6-60

INV. NO. 1476-W