

KANSAS
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

File No. _____ County: HAMILTON

Location: C. NE-SW Sec. 5 Twp. 2Y Rge. 4Y (E) (W)

Name of Field: _____ Total Depth: 2802'

I have this date completed supervision of plugging of:

Lease Name: PLUNKETT Well No. 1-5

Operator's Full Name: HAMILTON BROTHERS

Complete Address: 537 PETROLEUM BLDG AMARILLO, TEXAS

Plugging Contractor: CO TOOLS

Address: _____ License No. _____

Oil Well _____ Gas Well Input Well _____ SWD Well _____ D & A _____

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No

If yes how long? _____ Reason: _____

Operation Completed: Hour 5:00 PM Day 18 Month MAY Year 1961

The above well was plugged as follows:

7 7/8 - 284' circ - 4 1/2 - 2801' circ - Plug Back 2774 - TOP PERF 2702'
PUMPED 25 SYP CNT FROM 2774' TO 2454' - FILLED
W/SLUD. TO 193' - FILLED TO BASE OF CELLAR W/15
SYP CNT - NO PIPE RECOVERED AS 4 1/2 WAS CNT
CIRC - TO BASE OF CELLAR.

RECEIVED
STATE CORPORATION COMMISSION

JUN 2 1961 6-2-61

CONSERVATION DIVISION
Wichita, Kansas

Signed: Frank Brantford
Conservation Division Agent

Reviewed: Harold Green
Field Supervisor

Remarks:

INVOICED
DATE 6/16/61
INV. NO. 3189-W