1080385

		API NUMBER 1	5- 185-21,500-0000
To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		SW SW SW, SEC	• 31 , t 22 s, R 12 H 20 feet from S section line
	N'S PLUGGING REPORT	4050	feet from E section line
	7107		lewis Well g 1
	Dakota Resources, Inc.		Stafford 124.97
Name&	2900 Security Life Building		epth
	Denver, CO 80202		pe: Sizefeet
	· ·		ng: \$1ze 8 5/8 feet 259
• boodened	Oll Well X Gas Well		
	1 as hereinafter indicated		
	Contractor Kelso Casing Pulling	•	License NumberOOO
	Box 347, Chase, KS 67524		
	o plug at: Hour: 9:30 am Day:	 - _	
Plugging	proposal received from	Mike Gomez	
(company	name)Kelso		(phone) 316-938-2457
	Name) Kelso 1/2" at 3845' Perfs at 3502-08,		(phone) 316-938-2457
were: 40	1/2" at 3845' Perfs at 3502-08,		
were: 40	-	x cement on top o	of sand through bailer
lst plug 2nd plug	1/2" at 3845' Perfs at 3502-08,	x cement on top o	of sand through bailer
lst plug 2nd plug	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10	x cement on top o	of sand through bailer
lst plug 2nd plug	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s	x cement on top o	ement, 10 sx gel, 1 sack hulls,
lst plug 2nd plug release	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s	x cement on top of one of the second second second second by	of sand through bailer ement, 10 sx gel, 1 sack hulls,
lst plug 2nd plug release Plugging Operation	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Pro Operations attended by Agent?: s Completed: Hour: 10:30 ampay:	x cement on top of 0 sx ge1, 50 sx cement. posal Received by All Pa	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) art None May Year: 19 85
lst plug 2nd plug release Plugging Operation	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Pro	x cement on top of 0 sx ge1, 50 sx cement. posal Received by All Pa	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) art None May Year: 19 85
lst plug 2nd plug release Plugging Operation ACTUAL PL	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Pro Operations attended by Agent?: s Completed: Hour: 10:30 ampay:	x cement on top of 0 sx gel, 50 sx cement. posal Received by All X Pa 30 Month ack to 3450' and	ement, 10 sx gel, 1 sack hulls, (TECHN/CIAN) art None May Year:19 85 dumped 4 sx cement on top of
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Pro Operations attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded ba	x cement on top of 0 sx gel, 50 sx cement. posal Received by All Y Pa 30 Month ack to 3450' and ell with 3 sx hul	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) None May Year: 19 85 dumped 4 sx cement on top of 1s, 10 sx gel, 50 sx cement, 10
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Proposerations attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed we	x cement on top of 0 sx gel, 50 sx cement. posal Received by All Y Pa 30 Month ack to 3450' and ell with 3 sx hul	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) None May Year: 19 85 dumped 4 sx cement on top of 1s, 10 sx gel, 50 sx cement, 10
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Proposerations attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed we	x cement on top of 0 sx gel, 50 sx cement. posal Received by All Y Pa 30 Month ack to 3450' and ell with 3 sx hul	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) (TECHNICIAN
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr sx gel,	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 108 5/8" rubber plug and pump 125 s Plugging Propositions attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed well sack hulls, released 8 5/8" rul	x cement on top of 0 sx gel, 50 sx cement. posal Received by All Y Pa 30 Month ack to 3450' and ell with 3 sx hull be plug and pum	tement, 10 sx gel, 1 sack hulls, (TECHN/CIAN) (TECHN/CIAN) None May Year:19 85 dumped 4 sx cement on top of 1s, 10 sx gel, 50 sx cement, 10 Apped 125 sx cement PELEVED STATE CORPORATION COMMISSION JUN 1 7 1985
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr sx gel,	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Proposerations attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed well sack hulls, released 8 5/8" rul pressure 400 psi and shut in 50 p	x cement on top of 0 sx gel, 50 sx cement. posal Received by All Y Pa 30 Month ack to 3450' and ell with 3 sx hull be plug and pumpsi	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) (TECHNICIAN
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr sx gel,	1/2" at 3845' Perfs at 3502-08, sand back to 3450' and dump 4 so squeeze well with 3 sx hulls, 108 5/8" rubber plug and pump 125 s Plugging Propositions attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed well sack hulls, released 8 5/8" rul	x cement on top of 0 sx gel, 50 sx cement. posal Received by AllXPa30Month ack to 3450' and ell with 3 sx hull bber plug and pum psi	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) None May Year:19 85 dumped 4 sx cement on top of 1s, 10 sx gel, 50 sx cement, 10 aped 125 sx cement REFERING STATE CORPORATION COMMISSION JUN 1 7 1985 CONSERVATION DIVISION Wichita, Kansas
lst plug 2nd plug release Plugging Operation ACTUAL PL sand thr sx gel,	1/2" at 3845' Perfs at 3502-08, sand back to 3450! and dump 4 so squeeze well with 3 sx hulls, 10 8 5/8" rubber plug and pump 125 s Plugging Pro Operations attended by Agent?: s Completed: Hour: 10:30 ampay: UGGING REPORT 1st plug sanded be ough bailer, 2nd plug squeezed well sack hulls, released 8 5/8" rul pressure 400 psi and shut in 50 pused 160/40 Pozmix 2% gel 3% cc is	x cement on top of 0 sx gel, 50 sx cement. posal Received by AllXPa30Month ack to 3450' and ell with 3 sx hull bber plug and pum psi	ement, 10 sx gel, 1 sack hulls, (TECHNICIAN) None May Year:19 85 dumped 4 sx cement on top of 1s, 10 sx gel, 50 sx cement, 10 aped 125 sx cement REFERING STATE CORPORATION COMMISSION JUN 1 7 1985 CONSERVATION DIVISION Wichita, Kansas