Form CP-4 Rev. 12-15-80

STATE OF KANSAS STATE CORPORATION COMMISSION 200 Colorado Derby Bldg. Wichita, Kansas 67202

	COUNTY				24 TWP. 22 rom lines:	RGE	16 X /W
	Location a						
	Lease Owne	r <u>Vac</u> P	etrole	m			
					Wel:		B - 1
	•		•		ichita, KS 6		
	1		-		Gas or Dry	-	
					77/7/00		
					11/1/83		
	Plugging c					· · · ·	
	l l				/1/83	_	
Locate Well	keason ior	abandonii	ent or	well or pr	roducing for	mation_u	<u>ry</u>
correctly on above	T						
Section Platt.	•				servation D	lvision o	r it's
Name of Co.,	•	, ,,			ed? Yes	•	
Name of Conservation Age		_	_				
Producing formation				-		Ι.υ	
Show depth and thickness	s or all water	, orr and	. gas ro	nmactons.	• .		
OIL, GAS OR WATER RECORL							g Record
Formation	Content	From	To	Size	Put in	Pul	led Out
			 -				
or other plugs were used	e method or me d, state the c	thods use	d in ir	rcroducing	it into the	hold. I	f cement
fluid was placed and the or other plugs were used to feet for earlier from the feet fr	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & vsx in rathole.	thods use haracter spot 30s scc, mid to coden plu 10sx in	d in ir of same of sam	ntroducing e and depth O Roxmis, spot 50s; solid bride	it into the placed, from 2% gel, mud k 60-40 Pozm ge, pumped I	hold. I om to 980', ix, 2% ge 0sx to be	f cement feet
fluid was placed and the or other plugs were used to feet for earn drill pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & vsx in rathole.	thods use haracter spot 30s scc, mid to coden plu 10sx in	d in ir of same of sam	ntroducing e and depth O Roxmis, spot 50s; solid bride	it into the placed, from 2% gel, mud k 60-40 Pozm ge, pumped I	hold. I om to 980', ix, 2% ge 0sx to be	f cement feet
fluid was placed and the or other plugs were used to feet for earlier from drill pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/ of cellar, pumped 15	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & vsx in rathole.	thods use haracter spot 30s scc, mid to coden plu 10sx in	d in ir of same of sam	ntroducing e and depth O Roxmis, spot 50s; solid bride	it into the placed, from 2% gel, mud k 60-40 Pozm ge, pumped I	hold. I om to 980', ix, 2% ge 0sx to be	f cement feet
fluid was placed and the or other plugs were used to feet for earlier from the feet for earlier from 50sx 60-40 Pozm 3%cc, mud to 40', 1/of cellar, pumped 15	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & vsx in rathole.	thods use haracter spot 30s scc, mid to coden plu 10sx in	d in ir of same of sam	ntroducing e and depth O Roxmis, spot 50s; solid bride	it into the placed, from placed, from 2% gel, mud k 60-40 Pozm ge, pumped I	hold. I om to 980', ix, 2% ge 0sx to be	f cement feet
fluid was placed and the or other plugs were used to feet for ea Run drill pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/ of cellar, pumped 15 @ 5:30 AM, 11/1/83 b	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton.	thods use haracter spot 30s scc, mrd to coden plus 10sx in	d in ir of same ex 60-40 to 490 ng for s mouseho	ntroducing e and depth O Poxmis, , spot 50s; solid bride ole, 5sx in	it into the placed, from placed, from placed, from placed, mud k 60-40 Pozm ge, pumped la water well	hold. I om to 980', ix, 2% ge 0sx to ba . Comple	f cement feet
fluid was placed and the or other plugs were used to feet for ea Run drill pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/ of cellar, pumped 15 @ 5:30 AM, 11/1/83 b	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton.	thods use haracter spot 30s scc, mrd to coden plus 10sx in	d in ir of same sx 60-40 co 490 cm mouseho	ntroducing e and depth O Poxmis, , spot 50s; solid bride ole, 5sx in	it into the placed, from placed, from placed, from placed, mud k 60-40 Pozm ge, pumped la water well	hold. I om to 980', ix, 2% ge 0sx to ba . Comple	f cement feet
fluid was placed and the or other plugs were used to feet for ea Run drill pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/ of cellar, pumped 15 @ 5:30 AM, 11/1/83 b	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton.	thods use haracter spot 30s scc, mrd to coden plus 10sx in	d in ir of same sx 60-40 co 490 cm mouseho	ntroducing e and depth O Poxmis, , spot 50s; solid bride ole, 5sx in	it into the placed, from placed, from placed, from placed, mud k 60-40 Pozm ge, pumped la water well	hold. I om to 980', ix, 2% ge 0sx to ba . Comple	f cement feet
fluid was placed and the or other plugs were used to feet for ea Run drill pipe open	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton, al description ettor Cougar.	thods use haracter spot 30s cc, mid to coden plus 10sx in is neces Drilling	d in ir of same sx 60-40 co 490 cm mouseho	ntroducing e and depth O Poxmis, , spot 50s; solid bride ole, 5sx in	it into the placed, from placed, from placed, from placed, mud k 60-40 Pozm ge, pumped la water well	hold. I om to 980', ix, 2% ge 0sx to ba . Comple	f cement feet
fluid was placed and the or other plugs were used to	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton, ctor Cougar. COUNTY OF	is neces prilling Sedgwice (employ	d in ir of same sx 60-44 co 490 co 49	ntroducing e and depth O Roxmis, , spot 50s; solid brid ole, 5sx in use BACK of ac. ,ss. owner) or says: The	it into the placed, from placed, from placed, from placed, from per pumped I never well this sheet (SWASSPORP) at I have keep par I have keep placed in the	hold. I om to 980', ix, 2% ge 0sx to ba Comple	f cement feet feet feet feet ted fthe of the
fluid was placed and the or other plugs were used to	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton, ctor Cougar. COUNTY OF	is neces prilling Sedgwice (employ	d in ir of same sx 60-44 co 490 co 490 co	ntroducing and depth of Roxmis, spot 50s; solid bride ole, 5sx in the log of	it into the placed, from placed, from placed, from placed, from placed, from placed point in water well this sheet would be aboved.	hold. I	f cement feet 1, se ted of the of the well as
fluid was placed and the or other plugs were used feet for earling pipe open spot 50sx 60-40 Pozm 3%cc, mud to 40', 1/ of cellar, pumped 15 @ 5:30 AM, 11/1/83 b (If additional Name of Plugging Contract STATE OF Kansas John S. Crowe above-described well, be facts, statements, and recomposed to the composition commission same at Corporation commission	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton. ctor Cougar COUNTY OF eing first dul matters herein are true and	is necesorilling Sedgwice (employ y sworn of correct.	d in ir of same sx 60-40 co 490 co for smousehousehousehousehousehousehousehouseh	ntroducing and depth of Poxmis, spot 50s; solid bride ole, 5sx in the log of the log of lp me God. nature)	it into the placed, from placed, from placed, from placed, from per pumped I have well the above-dependent I have keep the abo	hold. I	f cement feet fee
fluid was placed and the or other plugs were used feet for each feet feet for each feet feet feet feet feet feet feet fee	e method or med, state the cach plug set. ended to 4084, ix, 2% gel, 3% 2 sx hulls & v sx in rathole, y Halliburton. ctor Cougar COUNTY OF eing first dul matters herein are true and	is necesorilling Sedgwice (employ y sworn of correct.	d in ir of same sx 60-40 co 490 co for smousehousehousehousehousehousehousehouseh	ntroducing and depth of Poxmis, spot 50s; solid bride ole, 5sx in the log of the log of lp me God. nature)	it into the placed, from placed	hold. I	f cement feet I, se ted of the of the well as hita6721